# EXHIBIT A

# IN THE UNITED STATES BANKRUPTCY COURT SOUTHERN DISTRICT OF NEW YORK

IN RE:	) Chapter 11 No. 12-12032	
GMAC MORTGAGE, LLC,	)  Jointly Administered under 1	No.
Delter	) 12-12020	
Debtor,	) ) Adversary No	
	)	

# UNIVERSAL RESTORATION SERVICES, INC.'S ADVERSARY COMPLAINT TO RECOVER MONEY PURSUANT TO RULE 7001(1) OF THE FEDERAL RULES OF BANKRUPTCY PROCEDURE

Plaintiff, Universal Restoration Services, Inc. ("Universal"), brings this action against Debtor/Defendant, GMAC Mortgage, LLC ("GMAC") pursuant to Rule 7001(1) of the Federal Rules of Bankruptcy Procedure to recover money being held in trust for Universal by GMAC, and in support thereof, Universal states as follows:

### PRELIMINARY STATEMENT

Universal is the plaintiff in a suit presently pending in the Circuit Court of Cook County, Illinois, Law Division (No. 11 L 004635) in which GMAC is a named defendant. The state court complaint against GMAC alleges (i) breach of fiduciary duty; (ii) breach of contract; (iii) fraud; and (iv) constructive trust (Counts I-IV, respectively). The state court action against GMAC has been moved to the "bankruptcy stay calendar" pending resolution of Universal's position in GMAC's bankruptcy. Through this adversary proceeding, Universal seeks a determination that monies GMAC holds for Universal in trust or escrow for the benefit of Universal (which is the basis for the state court complaint) are not "property of the estate" under § 541 of the United States Bankruptcy Code (the "Code").

### **JURISDICTION AND VENUE**

- 1. The Court has jurisdiction to hear this matter pursuant to 28 U.S.C. §157 and 1334 and 11 U.S.C §541. This is an adversary proceeding pursuant to Fed. R. Bankr. P. 7001(1) and a core proceeding pursuant to 28 U.S.C. §157(b)(2)(A) and (O).
  - 2. Venue is proper in this district pursuant to 28 U.S.C. §1409(a).

### **PARTIES**

- 3. Plaintiff, Universal, is an Illinois corporation, located in Cook County, Illinois.
- 4. Defendant, GMAC, is a mortgage provider and servicer and is an indirect, wholly owned subsidiary of Ally Financial Inc.

### STATEMENT OF FACTS

- 5. Universal's claims against GMAC arise out of a foreclosure action GMAC filed against Jorge Escobar ("Escobar"), No. 09 CH 07418 in the Circuit Court of Cook County, Illinois, Chancery Division ("Foreclosure Action").
- 6. Before GMAC filed the Foreclosure Action, Universal had filed and recorded its claim for mechanic's lien ("Mechanic's Lien") against Escobar's residential property which was the subject of the Foreclosure Action in the amount of \$54,936.32.
- 7. Universal was not named as a party in the Foreclosure Action, and therefore, it filed a motion to intervene and seeking leave to file its proposed answer and counterclaim to foreclose Mechanic's Lien, wherein Universal asserted the priority of its lien ahead of GMAC's mortgage.
- 8. The Mechanic's Lien was later resolved in the Foreclosure Action as part of a global agreement between Escobar, GMAC and Universal, pursuant to which Universal received

payment for that work from GMAC who had received funds from the Escobar's insurer to pay for work Universal performed at the property.

- 9. However, prior to the global agreement and prior to Universal's receipt of payment for the work, a fire occurred at Escobar's property causing new and additional damages.
- 10. Escobar and Universal thereupon entered into a written contract dated October 2, 2009 ("October 2, Contract"), whereby they agreed Universal would perform new and additional work on the property to repair the fire damage. A copy of the October 2, 2009 Contract is attached hereto as **Exhibit A**.
- 11. Universal prepared an estimate of \$109,410.52 for fire damage repair work to be performed on the mortgaged property.
- 12. As a result of the contract between Escobar and Universal, an insurance claim was submitted to Auto Club Insurance Association ("ACIA"), the insurer insuring the property for fire damage. ACIA accepted its coverage obligation, and approved Universal's \$109,410.52 initial estimate.
- 13. On or about August 21, 2009, ACIA insurance adjuster Karl Meinhardt communicated with Racquel Flores of GMAC regarding the initially approved \$109,410.52 Universal estimate.
- 14. At all relevant times GMAC knew and was aware of the scope of the property damage, knew that Universal was performing the work at the property pursuant to the October 2, 2009 Contract, and knew that Escobar and ACIA had agreed to Universal performing the work to repair the fire damage pursuant to the estimate.
- 15. On August 24, 2009, ACIA issued check no. 30709708 payable to the Escobars, GMAC *and Universal* in the amount of \$108,910.52, to pay Universal for the initial additional

repair work. A true and correct copy of the check is attached hereto as **Exhibit B**. The amount of the payment was based solely on Universal's estimate to repair the property, and it was mailed to Universal's home office.

- 16. To ensure timely payment to Universal, an oral agreement (subsequently incorporated into a court order in the Foreclosure Action) was made among counsel for the parties at a scheduled hearing in the Foreclosure Action whereby GMAC agreed to hold in escrow the \$108,910.57 of insurance proceeds to pay Universal for fire repair damage work it had contracted to perform.
- 17. Counsel for Universal, GMAC and Escobar orally agreed at the hearing in the Foreclosure Action that GMAC, in the capacity of an escrowee, would hold the said \$108,910.57 of insurance proceeds solely for the benefit of Universal ("Escrow Agreement"), and drafted an order reflecting that agreement.
- 18. Further, in connection with the Foreclosure Action, Universal, GMAC and Escobar entered into successive agreements whereby Universal would be paid for its earlier work and, that GMAC would receive the \$108,910.57 of insurance proceeds pursuant to the Escrow Agreement to pay Universal for fire damage repair work it had contracted to perform.
- 19. Accordingly, as stated above, on September 22, 2009, the Circuit Court of Cook County entered an agreed order in the foreclosure proceeding ("September 2009 Order"), drafted and agreed to by attorneys for Escobar, GMAC and Universal, stating that: "GMAC is receiving a fully negotiable check for \$108,910.52 for portion of prospective fire repair, to be held in escrow by GMAC & paid to Universal Restoration Services with customary draws as work proceeds." The foregoing September 2009 Order contemplated that the \$108,910.52 was only a portion of the cost of the prospective fire damage repair work to be performed by Universal. The Escrow

Agreement and the September 2009 Order also contemplated that GMAC would pay Universal customary construction draws as its fire damage repair work progressed. A true and correct copy of the Order is attached hereto as **Exhibit C**.

- 20. At the time the September 22, 2009 order was entered, Universal agreed that GMAC could take possession of the check for the insurance proceeds based on representations made at the hearing by counsel for GMAC that the funds would be held in escrow for Universal and based on the inclusion of that language in the order.
- 21. Therefore, it stands to reason that GMAC knew Universal expected to be paid from the escrow funds when it agreed to the entry of the September 2009 Order, and the language of the September 2009 Order constituted an express promise by GMAC to pay Universal for its work from the escrowed funds.
- 22. GMAC accepted the \$108,910.52 check issued by ACIA and on information and belief, negotiated the check and deposited the \$108,910.57 of insurance proceeds in GMAC's own operating or other account.
- 23. While the initial October 2, 2009 Contract was for the sum of \$109,410.52, on or about October 22, 2009, the October 2, 2009 Contract was amended by Universal and Escobar and increased to the amount of \$151,691.04 ("Amended October 22, 2009 Contract") for necessary repair of additional fire damage to the property that had been identified. A true and correct copy of the Amended October 22, 2009 Contract is attached hereto as **Exhibit D**.
- 24. <u>In reliance on the aforesaid representations</u>, agreements and the September 2009 Order, Universal began performing fire damage repair work at the property pursuant to the Amended October 22, 2009 Contract. Universal initially completed work for the amount of \$10,986.80, and sought payment from escrowed insurance proceeds being held by GMAC.

- 25. Despite Universal's foregoing request for payment, in violation of the Escrow Agreement, GMAC failed and refused to pay Universal the \$10,986.80 progress payment due and owing to Universal.
- 26. At some point, due to the Foreclosure Action, Escobar vacated the property and surrendered possession thereof to GMAC, thereby requiring that GMAC cooperate with Universal to coordinate the remaining work, which included giving Universal access to the property in addition to paying Universal pursuant to the Escrow Agreement and September 2009 Order.
- 27. In conformity with the Escrow Agreement and the September 2009 Order, Universal submitted its progress payment requests to GMAC upon completing a portion of fire damage repair work.
- 28. GMAC failed to make payments to Universal from the funds it held in escrow, despite repeated requests by Universal. Such requests and communications about payment included, but were not limited to, communications from Universal with Racquel Flores, an employee of GMAC, on the following dates: September 28, 2009; October 2, 2009; October 19, 2009; October 26, 2009; November 5, 2009; December 14, 2009; and December 15, 2009.
- 29. Beginning on December 29, 2009, Universal also began communicating with GMAC employee Susan Turner about payments due for the work completed and about remaining fire damage repair work to be performed.
- 30. On December 30, 2009, Susan Turner confirmed with Universal the scope of the work to be performed and completed by Universal.
- 31. Thereafter, Universal continued to communicate and/or attempt to communicate with GMAC through March 31, 2010. GMAC failed to make any payments to Universal despite the repeated demands.

- 32. Thereafter, counsel for Universal contacted counsel for GMAC regarding the outstanding payment and to obtain GMAC's cooperation to allow the balance of the work to proceed.
- 33. GMAC failed to cooperate or communicate with Universal thereby preventing Universal from completing the remaining work under the Amended October 22, 2009 Contract and failed to pay Universal from escrowed insurance proceeds for fire damage repair work already completed pursuant to said agreement.
- 34. On information and belief, GMAC has retained for its own benefit all of the insurance proceeds it received as escrowee and is obligated to pay Universal pursuant to the Escrow agreement and the September 2009 Order.

### **CLAIMS FOR RELIEF**

### **COUNT I**

### (Determination that Funds are not "Property of the Estate" under §541)

- 35. Plaintiff re-alleges and fully incorporates the allegations pleaded above as paragraphs 1-33 as if fully set forth herein.
- 36. Federal Rule of Bankruptcy Procedure 7001(1) states:

  "An adversary proceeding is governed by the rules of this Part VII. The following are adversary proceedings:
  - (1) a proceeding to recover money or property, other than a proceeding to compel the debtor to deliver property to the trustee, or a proceeding under § 554(b) or § 725 of the Code, Rule 2017 or Rule 6002."
- 37. Plaintiff, Universal brings this action pursuant to Rule 7001(1) to recover the funds being held in escrow by GMAC, as such funds are being held in trust for Universal and not "property of the estate" under § 541 of the Code.

- 38. The funds being held by GMAC are and at all relevant times have been held in trust for the benefit of Universal as re-affirmed and established as a matter of law by means of the September 2009 Order attached hereto as **Exhibit C**, and thus, such funds are not and never were property of GMAC's bankruptcy estate.
- 39. Universal is entitled to a turnover of said funds being held in trust by GMAC for its benefit in the amount of \$108,910.52.

### **COUNT II**

### (Promissory Estoppel)

- 40. Plaintiff re-alleges and fully incorporates the allegations pleaded above as paragraphs 1-33 as if fully set forth herein.
- 41. GMAC made a clear and unambiguous promise to hold the funds in escrow and pay Universal as work on the original October 2, 2009 Contract and work on the Amended October 22, 2009 Contract progressed.
- 42. Plaintiff relied on GMAC's promise to make payments from the funds held in escrow when it entered into the October 2, 2009 Contract and the Amended October 22, 2009 Contract, agreed to the entry of the September 2009 Order in the Foreclosure Action, and agreed to surrender possession of the check to GMAC.
- 43. Plaintiff's reliance on GMAC's promise was foreseeable; especially in light of the entry of the September 2009 Order and the express language contained therein.
- 44. Plaintiff's reliance on GMAC's promise was to its detriment; as of the current date, Plaintiff has yet to be paid for the work already performed on the property or to realize the expectancy of the Amended October 22, 2009 contract, for which GMAC promised payment was to be made from the escrowed funds.

1318112702Pmgng Ddeor 554006d 03Follend 3 0/25/163 ed 503/00124 3 0/25/4:341:502015 Ddeorhileith A Ppd 9 0 f 58

### **PRAYER**

WHEREFORE, Plaintiff, Universal Restoration Services, Inc., respectfully requests that the Court enter an order:

- (a) Declaring that the funds being held in escrow by GMAC are being held in trust for Universal and thus not property of the estate under § 541 of the Code;
- (b) Determining that GMAC is estopped from claiming said funds are property of the estate pursuant to the doctrine of promissory estoppel;
- (c) Directing GMAC to turn over said funds to Universal in the amount of \$108,910.52;
  - (d) Granting Universal any other and further relief to which it may be entitled.

**Dated: March 1, 2013** 

### LEVENFELD PEARLSTEIN, LLC,

By: /s/\_\_Jonathan P. Friedland\_\_

Jonathan P. Friedland [IL ARDC # 6257902] Mitchell Bryan [IL ARDC # 6183011] Jamie L. Burns [IL ARDC #6300120] LEVENFELD PEARLSTEIN, LLC 2 N. LaSalle St., Ste. 1300 Chicago, Illinois 60602

Phone: (312) 346-8380 Facsimile: (312) 346-8434

Counsel for Universal Restoration Services, Inc.

# **EXHIBIT A**



## AGREEMENT BETWEEN OWNER AND CONTRACTOR

This Agreement made on 10/02/09	***************************************
Belween the Owner:	Process
Name: JORGE ESCOBAR Address: 9640 LARAMIE SKOKIE, IL 600	57 57
and the Contractor.	
Universal Restoration Services, Inc. 390 Holbrook Drive Wheeling, IL 60090	
to complete the following work, repair or impro	ovement:
000 445-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	
	PRAMIE ST
at the Property located at: 9640 LA	PRAMIE ST 14 60077
at the Property located at: 9640 LA	PRAMIE ST 14 60077
at the Property located at:  9640 LA SKOKIE,  or the Agreed Contract Amount of: 50 % Down Payment:  Balance Owed:	\$ 109, 410.52 \$ (required)
or the Agreed Contract Amount of: 50 % Down Payment:	\$ 109 410.52 (required)
or the Agreed Contract Amount of: 50 % Down Payment: Balance Owed:	\$ 109, 410. 52. \$ (required) \$ 109, 410. 52. \$ (required) \$ 209, 410. 52.
or the Property located at: 9640 LA SKOKIE,  or the Agreed Contract Amount of: 50 % Down Payment:  Balance Owed: alance to be paid to Universal Restoration Se	\$ 109 410.52 (required)

# Dec 15506 Filed Folso 10/35/12 hte Feytors of 10/35/1359: 05 kni fix height i bit

19/21/2009 13:11

1.1153448783

32/48

Universal Restoration Services

190 Holbrook Drive Vbeeling, IL 60090 Phone (888) 877-6766 Pax (888) 596-4996

Clients

lorge Escober

Property:

9640 Lammie Street

9kokie, IL 60077

Operator Info:

Operators **BBAVARO** 

Estimators

Brian Bavaro

Businesa: (847) 561-6342

Type of Estimate:

Water Danuage

Date Entered: 3/10/2009 Date Assigned:

Price Lists CHICAGO 2009\_IST\_QTR

Restoration/Service/Remodel

Estimatos

45669-ESCOBAR-CODE

### OUR MISSION & UNIVERSAL RESTORATION SERVICES

Universal Restoration Services aspires to remove stress and uncertainty that occur when a property damage loss affects your life.

Restoring property utilizing the highest morals and ethics.

Serving our customers with excellence to ensure satisfaction.

10150448780

HIE - 13748




### Universal Restoration Services

390 Holbrook Drive Whealing, IL 60090 Phone (888) 877-6766 Fax (888) 596-4996

### 19669-ESCOBAR-CODE

Basement



Garage

504.67 SF Walls

393.00 SF Walls & Ceiling

Celling Height: 8'

188.33 SF Centing 338.33 SF Floor

	43.15 SY Flouring 78.83 LF Ceil Perimeter		60.83 LF Floor Pe	rimeter
Masing Wall: 1 - 18'0" X 7'0"	Opens into Exterior		Goes to Floor	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
5/8" drywall - hung & fire taped only	38 <b>8.33</b> SF	3.00	1.28	497.06
1/2" drywail - hung & fire taped only	504.67 SP	Э. <b>ОО</b>	1.18	595.51
Batt insulation + 6" - R19	504.67 SP	0.00	0.72	363.36
Clean stud wall	304.67 SP	0.00	0.56	232.62
Seal stud wail for odor control	504.67 SF	9.00	0.61	307.85
Seal floor or ceiling joint system	188.33 SF	9.00	0.73	233.48
Clean with pressure/chemical spray	38 <b>8.33 SF</b>	9.00	0.27	104,85
Overhead (garage) door opener - Detach & reset	1.00 EA	9.00	178.34	178.34
Cabinetry - upper (wall) units	3.67 LF	9.00	117.97	1,022,80
R&R Exterior door - metal - insulated - flush or panel style	1.00 EA	17.35	270.95	238.30
RAR Door lookset - existing	1.00 EA	9,72	46.63	56.35
Stain & finish casing	17.00 LF	0.00	1.10	18.70
Paint door slab only - 2 coats (per side)	1.00 EA	0.00	21.43	21.43
Paint door or window opening - 2 costs (per side)	1.00 EA	0.00	21.49	21,49
Electrical				
R&R Ground fault interrupter (GFI) outlet	2.00 EA	3.51	28.35	63.72
R&R Switch	2.00 EA	3.91	15.46	38.74
R&R Outlet - High grade	1.00 EA	3.91	20.86	24,77
These need to be tumper resistant devices per t	he NEC 2008 code.			,,,,
R&R Porcelain light fixners	1.00 EA	6.48	29.58	36.06
RAR #14 to #16 gauge copper wire -	150, <b>00 L.P</b>	0,34	0.75	163,50
tranded or solid			3.7 <b>.</b>	; (Jac.) (A
R&R Central vacuum - cleaning system -	1.00 EA	180.01	2,946.09	3,125.10
669-ESCOBAR-CODE			7/8/2009	Page;

. a153448783

14/48 E


### UNIVERSAL

### Universal Restoration Services

190 Holbrook Drive Wheeling, IL 60090 Phone (888) 877-6766 Pax (888) 596-4996

### CONTINUED - Garage

DESCRIPTION	YTAĢ	REMOVE	REPLACE	TOTAL
HVAC			***	
l'ouis: Garage				7,495.03



	Foreace RM	Criling Height: 8
21°12'8' + 31°-4	164.00 SF Walls	31.50 SF Ceiling
120	195.50 SF Walls & Ceiling	31.50 SF Floor
Tremma Att	3.50 SY Flooring	20.00 LF Floor Perimeter
[-x-+x]	23.00 LF Ceil Porimeter	
11. 1-21-4 11-2-4-12-1	23.00 LF Ceil Parimeter	

Missing Wall: 1 - 3'0" X 6'8"	Opens into Exterior		Goes to Floor	
DESCRIPTION	QNTY	REMOVE	HEPLACE	TOTAL
Sign drywall - hung, taped, floated, ready for paint	1.50 SP	0.00	1.64	51.66
1/2" drywall - hung, taped, floated, ready for paint	164.00 SF	0.00	1.54	252.5 <b>6</b>
But insulation - 6" - R19	31.50 SF	0,00	0.72	22,68
Clean stud wali	164.00 SF	0.00	0.56	91.84
Scal stud wall for odor control 15669-ESCOBAR-CODE	164,00 SF	0.00	0.6 <b>1</b> 7/8/ <b>2009</b>	100.04 Page; 3

13153448783

TE 75749

### UNIVERSAL Universal Restoration Services

190 Holbrook Drive Vheeling, IL 60090 Those (888) 877-6766 Fax (888) 596-4996

### CONTINUED - Formace RM

DESCRIPTION	QNTY	REMOVE	REPLACE	FOTAL
Scal floor or ceiling joist system.	31.50 SF	9.00	•).73	23.00
Seal then paint the walls and ceiling (2 coats)	195.50 SF	0.00	9.68	132.94
Paint door slab only - 2 costs (per side)	1.00 EA	3,0 <b>0</b>	21,43	21.43
Vinyl tile	31.50 SF	0.00	1 15	79.23
Bascboard - 2 1/4"	19.00 LF	0.00	2,49	24.90
Seal & paint baseboard - (we coats	10,00 LF	1.00	0.99	9.90
R&R Casing - 2 1/4"	17.60 LF	3.39	1.65	34,68
Scal & paint cusing - two coats	17.00 LF	v.v <b>o</b>	ა.9 <b>9</b>	16.83
Electrical				
110 volt copper wiring run 1/2"conduit 151f box/plug/switch	1,00 EA	0.00	118.53	118.53
HVAC				
R&R Furnace - forced sir - 125,000 BTU	1.00 EA	48.92	1,805.62	1.854.54
imace sustained damage from the water and has	quit-working.			
RAR Furusce vent - aluminum, 3"	3.00 LF	0.48	10.53	48.0
Replace the exhaust vent to the water heater.				
&R Furnace vent - double wall, 6"	35.0 <b>0 LF</b>	9.9 <b>5</b>	3 <b>0.02</b>	1,083.95
Coplace the flue serving the furnace and water her	ster.			
R&R Ductwork system - hot or cold air - 500 to 2199 SF bome	1.00 EA	38 <b>3.80</b>	5,019.27	5,408.07
Duct system has sustained damage from the water	. It is starting to oxid	ize and will rust over tir	ne.	
L&R Coil - 2 ton - ensed	1.00 EA	-14.18	185.16	329.34
leat, vent, & air conditioning repair - Ainimum charge	1.00 EA	U.0 <b>0</b>	335.00	335.00
To recover refrigerant and recharge unit.				
Yumbing				
L&R Humidifier unit	1.00 EA	29.33	596.72	626.05
&R. Water heater = 40 gallon = Gas = 12 yr	1.00 EA	14,97	1,125.49	1,170,46
Cotals: Furnace RM				12,095.71

45669-ESCOBAR-CODE

7/8/2009

Page: 4

13153448793

ास्य ८६७४स

### UNIVERSAL

467

### Universal Restoration Services

390 Holbrook Drive Vheeling IL 60090 Phone (888) 877-6766 31x (888) 596-4996



### Laundry Room

Calling Height: 8"

125.33 SF Walls 134.00 SF Walls & Cailing 5.52 SY Flooring 9.67 SF Ceiling

30.67 LF Ceil. Perimeter

27.67 LF Floor Perimeter

Missing Wall: 1 - 3'9" X 6'8"	Opens into Exteri	or .	Goes to Floor	
DESCRIPTION	QNTY	REMOVE	HEPLACE	TOTAL
5/8" drywall - hung, toped, floated, ready for paint	48.67 SF	0.00	1.54	<b>%.21</b>
1/2" drywall - hung, taped, floated, ready	225.33 SF	9.00	1.54	347.01
Ban insulation - 6" - RI9	38.67 SF	3 00	0.72	12.24
Clean stud wall	225.33 SF	0.00	0.56	126.18
Seal stud wall for odor control	225.33 SF	9.00	0.61	137.45
Scal floor or coding joint system	58.67 SF	0.00	0.73	
Scal then paint the walls and ceiling (2 couts)	284.00 SF	0.00	0.68	193.12
Paint door slab only - 2 coats (per side)	1.00 EA	0.00	. 21.43	21.43
(Install) Shelving - 12" - in place	4.00 LF	9.00	5.44	21.76
(Instali) Cabinetry - upper (wall) units	6:50 LF	0.00	34,94	227.11
Install) Dryer - Gas - Standard grade	1.00 EA	0.00	185.51	185.51
Install) Washer - Top-loading	1.00 EA	0.00	139.14	139.14
Baseboard - 2 1/4**	27.67 L.F	0.00	2,49	58.90
Base shoe	10.00 LF	0.00	1.24	12.40
eal & pains baseboard w/cap &/or shoe -	27.67 LP	5.0 <b>0</b>	1.18	32.65
Viny <b>t üle</b>	58.67 SF	0,00	3.15	(34.8)
Electrical				(34.61
&R Breaker panel - 100 mp	1 00 EA	375.00	68 <b>7.77</b>	1,062,77
R&R #Z gauge copper wire - stranded or olid	15.00 LF	0.42	2.96	50.70
Teed to replace panel due to water damage.				
10 volt copper wiring run 1/2"conduit 151f box/plug/switch	1.00 EA	ð. <b>00</b>	118.53	118.53
L&R Switch	2.00 EA	3.91	15.46	38,74
Install) Light fixture	1,00 ÉA	0.00	38.17	38.17
669-ESCOBAR-CODE			∴8/2009	Pages

3/21/1009 10:11

1,3153448783

TE 37/40

### WIVERSAL

### Universal Restoration Services

320 Holbrook Drive Viceling, IL 50090 Thone (888) 877-6766 Fax (888) 596-4996

### CONTINUED - Laundry Room

EA EA	9. <b>00</b>	74.65	TOTAL 71.65
7A			
	3.62	92.57	101,19
; <b>A</b>	.1.00	. 7 . 70	
	<b></b>	04.75	1,255.60
E	EA	EA 0.00	EA 0.00 62.78

Basement Ceiling Height: 8'

413.33 SF Walls 166.83 SF Ceiling
580.17 SF Walls & Ceiling 166.83 SF Floor
18.54 SY Flooring 51.67 LF Floor Perimeter

51.67 LF Ceil. Perimeter

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
5/8" drywnii - hung & fire taped only	166.83 SF	0.00	1.28	213,54
1/2" drywall - hung, taped, floated, ready for paint (**	413.3 <b>3 SF</b>	9.00	1.54	636.53
Clean stud wall	413.33 SF	0.00	0.56	231,46
Scal stud wait for odor control	413.33 SF	0.00	0.61	252.13
Scal floor or ceiling joist system	166.83 SF	0.00	0.73	121.79
Seal then paint the walls and ceiling (2 coats)	5 <b>80.17 SF</b>	0,00	0.68	394.52
Saseboard - 2 1/4"	51.67 LF	0.00	2.49	123.66
Seal & pann baseboard - two coats	51. <b>67 LF</b>	0.00	0.99	51.15
Carpet	191.86 SF	0.00	3.03	581.14
5 % waste added for Carpet.			****	J 19 8 - 19-4
Carpet pad	166.83 SP	0.00	0.53	38.42
R&R Casing - 2 1/4*	17.00 LF	0.39	1.65	34.68
ical & paint casing - two coats	7.00 LF			16.83
Perach & Ruser Window blind - horizontal of vertical - Large	J.00 EA	0.00	0.00	35.51
669-ESCOBAR-CODE			7/8/2009	Pager

# 

· M 217 2009 (13:11

14153449793

136E 13740



### Universal Restoration Services

90 Holbmok Drive Wheeling, IC 60090 Phone (888) 877-6766 Fax (888) 596-4996

### CONTINUED - Besement

DESCRIPTION	ONTY	REMOVE	REPLACE	TOTAL
Electrica).		• • • • • • • • • • • • • • • • • • • •	<del>varantial estate de la constantial de la consta</del>	
R&R Switch	1.00 EA	3.91	15.46	19.37
R&R Outlet - High grade	4.00 EA	3.91	30.8 <b>6</b>	>9.08
These need to be tamper resistant devices per ti	he NEC 2008 code.			
Install) Light fixture	2.00 EA	, a <b>0.00</b>	33.17	75,34
R&R Smoke detector - High grade	1.00 EA	3.62	31.54	20.16
%R#14 to #16 gauge copper wire - transfed or solid	150,00 LF	0.34	9.75	163.50
Totals: Basement				3,235.01

-3' o' 4 Basement Sta		Å.	Ceille	g iteighte 17
	152.00 SF Wells		27:00-SP Ceiling	
	279 00 SF Walls & Ceiling		55.98 SF Floor	
	6.22 SY Flooring 21.00 LF Ceil Perimeter		25.46 LF Floor Peri	meter
Missing Wall: 1- 3'0" X 17'0"	Opena into Lunding	v .	Goes to Floor/Ceiling	<b>}</b> *
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
R&R 5/8" drywell - hung, taped, floated, ready for paint	27.00 SF	0.33	1.64	53.19
1/2" drywall - bung, usped, floated, ready for paint	2.5 <b>2.00 SF</b>	0.00	1.54	388.08
Cless stud wall	252.00 SF	0.00	0.56	141.12
Scal stud wall for odor control	252.00 SF	0.00	0.61	153.72
Scal floor or ceiling joist system	5 <b>5.98 SF</b>	0.00	0.73	40.87
Seal/prime more than the floor perimeter - one cost	76.37 SF	0.00	0.37	28.26
Paint the walls - one coat	25 <b>2.00 SF</b>	0.00	0.40	:00.80
Carpet	64.38 SF	9.00	3.03	195.07
15 % waste added for Curpet.				
Carpet pad	55.98 SF	0,00	0.53	29.67
Totals: Basement Sta		Water Committee		1,130.78
669-ESCOBAR-CODE			7/8/2009	Page

19153448783

"军"的/胡



### Universal Restoration Services

20 Holbrook Drive Vheeling, IL 60090 Phone (888) 877-6766 Fax (888) 596-4996



ading			
	***************************************		
	104.00	SF	Walls

Ceiling Height: #1


119.00 SF Walls & Ceiling 1.67 SY Flooring 15.00 SF Ceiling 15.00 SF Floor

13.00 LF Ceil, Perimeter

13.00 LF Floor Perimeter

Missing Wall: 1 - 3'0" X gron	Opens into Basen	neat Sta	Goes to Floor/Cellin	ľ
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
R&R 5/8* drywall - hung, inped, fkusted, cody for paint	15.00 SF	<b>3.33</b>	1.64	29.55
1/2" drywall - hung, taped, floated, ready for paint	104.00 SF	0.00	1.54	160.16
Clean stud wall	104.00 SF	0.00	0.56	58.24
Seal stud wail for odor control	104.00 SF	9. <b>00</b>	0.61	53,44
Seal floor or ceiling joist system	15.00 SF	0.00	0.73	10.95
Scal/prime the walls and coiling - one coat	119.00 SF	0.00	0.37	¥4.03
Print the walls and ceiling - one coat	119,00 SF	0.00	0.4 <b>0</b>	47.60
Carpet	17.25 SF	0.00	3.03	52.27
5 % waste added for Carpet.			<i>1</i>	74121
Carpet pad	15.00 SF	0.00	9.53	7.95
Baseboard - 2 1/4"	13.00 LF	0,00	2.49	32.37
Seal & paint baseboard - two costs	13.00 LF	9.00	0.99	12.87
Totals: Landing				519.43
Total: Basement	S. A. C. S.			29.150.56

### First Floor



16153448793

(差 13/49)

### • Universal Restoration Services

20 Holbrook Drive Viceling, IL 60090 Chane (888) 877-6766 Ex (888) 596-4996

### CONTINUED - Stair

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
R&R 5/8" drywait - hung, taped, floated, ::endy for paint	6.00 SF	0.33	1.54-	11.82
1/2" drywail - hung, taped, floated, ready for paint	30.0 <b>0 SF</b>	0.00	1.54	123.20
Clean stud wall	74.00 SF	3.00	0.56	41.44
Scal stud wall for odor control	74.00 SF	0.00	0.61	<b>45.14</b>
Scal floor or ceiling joist system	33,50.SF	0.00	0.73	24,46
Sout/prime the walls and ceiling - one coat	30.00 SP	0.00	0.37	29.60
Paint the walls and ceiling - one cost	30.0 <b>0 SP</b>	0.00	0.40	32.00
Carpet	38.52 SF	0.00	3.03	116.72
15 % waste added for Carpet.				
Carpet pad	33.50 SF	0.00	0.53	17.76
Totale: Stair				412,14

The Car		Landing		<b>v</b>	Ceil	ing Helght: 9'
			219.21 SF Walls		54.26 SF Ceiling	<del></del>
I E E			273.47 SF Walls & Cailing		54.26 SF Floor	•
	ļ		5.03 SY Flooring		25.83 LF Floor Peri	imet <b>er</b>
			25.83 LF Ceil, Périmeter			
Missing Walls	1 -	3.6. X a.0.	Opens late Stair2		Goes to Floor/Critisa	
Missing Wall:	1 -	2'9" X 4'10"	Opena late Exterior		Goes to neither Floor	r/Ceiling
Missing Watt:	1 -	3'0" % 9'0"	Opens Into Stair		Goes to Floor/Celling	t
DESCRIPTION			QNTY	REMOVE	REPLACE	TOTAL
R&R 5/8" drywali - ready for paint	- hung,	taped, floated,	>4.26 SF	0.33	1.64	106.90
1/2" drywail - hung for paint	, taped,	, floated, ready	2 <b>73.47 SF</b>	9.00	1.54	421.14
Clean stud wali			219.21 SF	0.00	0. <b>56</b>	122.76
Seal stud wall for o	dor con	ions	219.21 SF	0.00	0,61	133.72
	joist s	ystem.	54.26 SF		0.73	39.61
Scal/prime the walls	s and ca	eiling - one cost	27 <b>3.47</b> SF	0.00	0.37	101.18
Batt insulation - 4"	- R13		72.00 ST	9.90	0.58	41.76
45669-ESCOBAR-CO	DDE				7/8/2009	Page: 9

13153449783

"证 11/40




### Universal Restoration Services

390 Holbrook Drive Wheeling, IL 60090 Phone (888) 877-6766 Fax (888) 596-4996

### CONTINUED - Landing

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Print the walls and ceiling - one cost.	273.47 SF	0.00	0.40	109.39
Carpet	62.40 SF	0.00	3 <b>.03</b>	139.07
15 % waste added for Carpet.				, - , , ,
Carpet pad	54.2 <b>6 SF</b>	0.00	0.53	28,76
Baseboard - 2 1/4"	25.83 LF	9.00	2,49	54.32
eal & paint baseboard - two costs	25.83 LF	0.00	0.99	25.57
Electrical				
Tostall) Light fixture	1.00 EA	0.00	38.17	38.17
R&R Smoke detector - High grade	1.00 EA	8.62	31.54	90.16
R&R Switch	2,00 EA	3.91	15,46	38.74
R&R#14 to #16 gauge copper wire - tranded or solid	90.00 £.F	0 34	0.75	28.10
Fouls: Landing				1.649.35



zir	Z		

151.08 SF Wells

166.33 SF Walls & Ceiling

4 86 SY Flooring

13.17 LF Ceil Perimeter

Ceiling Height: 17'

15.25 SF Ceiling 43.74 SF Floor

21.01 LF Floor Perimeter

Missing Walk 1 - 3'0" X 17'0"	ig Wall: 1 - 3'0" X 17'0" Opens into Landing Goes		Goes to Floor/Collins	to Floor/Ceiling	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL	
R&R 5/8" drywall - hung, taped, floated, ready for paint	15.25 SF	0.33	1.64	30.04	
1/2" drywell - hung, taped, iloated, ready for paint	166.33 SF	0.00	1.54	256.15	
Clean stud wall	151.08 SF	0,00	0.56	34.60	
Scal stud wall for odor control	151.08 SF	0.00	0.61	92.16	
Scal floor or ceiling joist system	43.74 SF	0.00	0.73	31.93	
Scal/prime more than the floor perimeter -	6 <b>3.03 SF</b>	0.00	0.37	23.32	
Paint the walls - one cost	151.08 SF	0.00	0.40	50.43	
Carpet	50.30 SF	0.00	3.03	152.41	
5669-ESCOBAR-CODE			7/3/2009	Page: I	

第二12/48

### Universal Restoration Services

390 Holbrook Drive Wheeling, IL 60090 Phone (888) 877-6766 Fax (888) 596-4996

### CONTINUED - Stair 2

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
15 % waste added for Carpet:		11.		······································
Carpet pad	43.74 SF	9.00	0.53	23.18
Totals: Stair2				754.22

Front layer

194.33 SF Walls 228.33 SF Walls & Ceiling

1.78 SY Flooring 26.00 LF Ceil Perimeter Ceiling Height: 8'

04.00 SF Ceiling 34.00 SF Floor

23.50 LF Floor Perimeter

21,000	Abov.			
Missing Walls 1 - 2'6" X 6'8"	Opens Into Exterior		Gues to Floor	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
R&R 5/8" drywall - hung, taped, floated, ready for paint	34.0 <b>0 SF</b>	0.33	1.64	56.98
1/2" drywell - hung, taped, floated, ready for paint	228.33 SF	0.00	1.54	351.6 <b>3</b>
Clean stud wall	194:33 SF	0.00	0.56	103.82
Seal stud wall for odor control	194.33 SF	0.00	0.61	118.54
Seal floor or ceiling joist system	34.00 SF	0.00	0.73	24.82
Seal/prime more than the floor perimeter - one cost	70.50 SF	0.00	0.37	26.09
Paint the walls - one cost	194.33 SP	<b>5.09</b>	0.40	77.73
Baseboard - 2 1/4*	23.50 LF	9,00	2,49	58. <b>52</b>
Base abox	10.0 <b>0 L.F</b>	0.00	1.24	12.40
Seal & paint baseboard w/cap &/or shoe - two coals	23.50 LF	6.00	1.18	27.73
1/4* Coment board	34.00 SF	0.00	3,52	119.68
Ceramic tile	3 <b>4.00 SF</b>	9.00	10.61	160.74
Underlayment - 1/4" BC plywood	34.00 SP	0.00	1.33	45.22
R&R Exterior door - metal - insulated - flush or panel style - flush	1.00 EA	17.35	270,95	288.30
NOTE Door and door jamb where damage by fix	e department.			
Door lockset & deadbolt - exterior - Detach & reset	1.00 EA	0.00	33.17	33.17
5669-ESCOBAR-CODE			7/8/2009	Page: I

18153448783

13748

### LVIVERBAL

### Universal Restoration Services

790 Holbrook Drive Wheeling, IL 60090 Phone (888) 877-6766 Fax (888) 596-4996

### CONTINUED - Front foyer

DESCRIPTION	ONTY	REMOVE	REPLACE	TOTAL
Paint casing - one cost	17.00 LF	0.00	0.66	11,22
Paint door slab only - 2 coats (per side)	2.00 EA	3 <b>00</b>	21.43	12.86
Faint door or window opening - 2 coats per side)	1.00 EA	<b>0</b> 0.0	21.49	.21.49
Electrical				
110 volt copper wiring run 1/2"conduit 15if box/plug/awitch	3.00 EA	ბ.00	(18.53	355,59
R&R Dimmer switch	1.00 EA	3.91	34.71	. 8.6 <b>2</b>
R&R Timer switch	1.00 EA-	3.91	31.73	35.64
Totals: Front foyer	1.00 EA	J.71	31.73	KOMIS

	177	<b>:</b>
	— 1231' —— <del>1</del>	11
, de .	Shirtan.	5
1	r	16
11		ન 11 24

Kitchen

323.47 SF Walls

446.18 SF Walls & Coiling

13.63 SY Flooring 44.83 LF Ceil, Perimeter Celling Height: 8'

122.71 SF Ceiling 122.71 SF Floor

42.33 LF Floor Perimeter

skaW gnieziM.	1 - 1'6" X 6'8"	Opens lato Exterior		Gues to Floor	
Missing Walls	1- J'10" X 4'10"	Opens into Exterior		Goes to weither Floo	r/Ctiling
DESCRIPTION		QNTY	REMOVE	REPLACE	TOTAL
5/8" drywall - hung, t for paint	aped, floated, ready	122.71 SF	0.00	1.64	201.24
1/2" drywall - hung, t for paint	aped, floated, ready	323.47 SF	0.00	1.54	498.14
Clesia stud wall		323.47 SF	0.00	0.56	181.14
Scal stud wall for odo	r control	323.47 SF	0.00	0.61	197.32
Scal floor or ceiling jo	ist system	122.71 SF	0.00	0.73	<b>39.58</b>
Batt insulation - 4" - F	U3	323.47 SF	0.00	0.58	187.61
Scal/prime the walls a	nd ceiling - one cost	446.18 SP	0.00	0.37	165.09
Pains the walls and co	iling - one coas	446.1 <b>2</b> SF	0.00	9.40	178.47
RACK Cabinetry - upp	or (wail) units	17.75 LF	5,84	117.97	2,197.63
R&R Cabinetry - lowe	z (base) units	15.75 L.F	5.84	156.35	2,554.49
R&R Countertop - Pla	t laid plastic laminate	13.42 LF	3.35	41.02	595,45
669-ESCOBAR-COD	E			7/8/2009	Page: I

18153448783

三国田 直見初

### UNIVERSAL

### Universal Restoration Services

100 Holbrook Drive Vheeling, IL, 60090 Thone (888) 877-6766 Tax (888) 596-4996

### CONTINUED - Kitchen

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Detach & Reset Sink - doubte	1.00 EA	0.00	s) 2 00	0.00
RAR Sink - double	1.00 EA	15.55	31 <b>5.5</b> 5	331.10
R&R Hacksplain - plastic laminate	4.03 SF	0.71	3.20	27.85
R&R Corner trim - stain grade	17.75 <b>L.F</b>	0.13	2.13	(0.12
Stain & finish corner trim	17.75 LF	9.00	1.10	19.53
Add for lazy susan	1,00 EA	0.00	56.37	56.37
Add-on for mitered corner (Countertop)	1.00 EA	0.00	30.53	80,53
Detach & Reset Cooktop - gas	1.00 EA	0.00	0.00	157.74
Detach & Reset Refrigerator - top freezer - 22 to 25 of	1.00 EA	7.00°	0.00	5 <b>7.32</b>
Tabinet knobs or puils - Detach & reset	24.00 EA	0.00	2.21	53,04
Baseboard - 2 1/4"	42.33 LF	0.00	2.49	105.40
Base shoe	10:00 LF	0.00	1.24	12.40
ical & paint baseboard w/cap &/or shoe -	42.33 LF	9.00	1.18	49.95
wo costs Inderlayment = 1/4" BC plywood	122.71 SF	9.00	1.33	163.20
/4" Cament board	122.71 SF	0.00	3.52	431.94
Ceramic tile	122.71 SF	0.00	10.61	1,301.95
&R Casing - 2 1/4"	17.00 LF	0,39	1.65	34.68
eal & paint casing - two coats	17.00 LF	0.00	0.99	16.83
sint door or window opening - 1 cost (per	1.00 EA	0.00	14.51	14.51
licetrical				
C&R 110 volt copper wiring run, box and outlet	1.0 <b>0 EA</b>	4.17	31.83	86.0 <b>0</b>
en hood connection.				
AR Ground fault interrupter (GFI) outlet	4.00 EA	3.51	28.35	127,44
&R Outlet - High grade	3.00 EA	3.91	20.86	74.31
hese need to be temper resistant devices per the	NEC 2008 code.			
A:R Switch	4.00 EA	3.91	15.46	77.48
Install) Light fixture	1.00 EA	0.00	38.17	38.17
Install) Ceiling fan without light	1.00 EA	0.00	154.58	154.58
AR #14 to #16 gauge copper wire •	330.00 LF	0.34	<b></b>	359.70
Plumbing				

45669-ESCOBAR-CODE

7/8/2009

Page: 13

9/21/1929 1J:11

19193448783

%E 13/43



### Universal Restoration Services

300 Holbrook Drive Wheeling, IL 60090 Phone (888) 877-6766 Fax (888) 596-4996

### CONTINUED - Kitchen

DESCRIPTION	ONTY	REMOVE	REPLACE	TOTAL
RAR Refrigerator/icemaker water supply	1.00 EA	3 89	124.55	: 28,44
Dishwasher connection	1.00 EA	0.00	144.07	: 44.07
(Install) Garbage disposer	1.00 EA	0.00	119.93	119.93
(Install) Sink - double	1.00 EA	0.00	1-14.32	144.32
Install) Sink strainer and drain assembly	2.00 EA	0.00	13.39	56.78
Detack & Reset Sink faucet - Kitchen	1.0 <b>0 EA</b>	9.00	0 00	128.43
Totals: Kitchen				11.650.77

)	*******	Dining Rese	•		Cein	lng Height: 8'
Property of			208.00 SF Walls		171.78 SF Ceiling	
'''	-11		479.78 SF Walls & Ceiling		171.78 SF Floor	
i i Estimbi			19.09 SY Flooring		41.83 LF Floor Peri	meter
1			14.33 LF Ceil. Perimeter			
tlicW paiecilM.	1.	12'4" X 8'0"	Opens into Exterior		Goes to Floor/Calling	
Missing Walls	1 -	6'0" X 5'0"	Opens late Exterior		Goes to neither Floor	r/Ceiling
Missing Walls	1 -	2'6" X 6'8"	Opens into Exterior		Goes to Floor	
Missing Walls	1 -	2'6" X 8'0"	Opens into Exterior		Goes to Floor/Ceiling	t
DESCRIPTION			QNTY	REMOVE	REPLACE	TOTAL
5/8" drywaii - hun for paint	g, uped,	floated, ready	17 <b>t.78</b> SF	9 <b>.00</b>	1.64	281,72
1/2" drywail - hun for paint	ıg, ı <del>sped</del>	, floated, ready	30 <b>8.00 SF</b>	0.00	1.54	474,32
Clean floor under	layment		171.78 SF	3.00	0.32	54.97
Scal underlaymen	t for ode	r control	171.78 SF	0.00	0.41	70.43
Clean stud wail			30 <b>8.00 SF</b>	9.00	0.5 <b>6</b>	172.48
Seal stud wail for	odor con	etrol	108.00 SF	0.00	0,61	137.88
Scal floor or ceilir	ng joist s	ystem	171.78 SF	9.00	0.73	125.40
Batt insulation - 4	" RIJ	-	30 <b>8.00 SF</b>	0.00	0.58	178.64
Balustrade				0.00	114.29	1,457.20
Stain & fivish bah	istrado		12.75 <b>LF</b>	0.00	30.7 <b>0</b>	263.93
669-ESCOBAR-C	ODE				7/8/2009	Page: 14

# 

9/21/2009 13:11

19152448783

11 選 (5749)



## Universal Restoration Services

190 Holbrook Drive Viceling, IL 60090 Phone (888) 877-6766 Fx (888) 596-4996

### CONTINUED - Dining Room

DESCRIPTION	QNTY	REMOVE	KEPLACE	TOTAL
Dalustrade top rail - Average grade - Material only	12.75 LF	0.00	12.50	150,65
Paint plywood sheathing	10 00 an			
Seal then paint the ceiling (2 coats)	20.00 SF	0:00 <sub>Va.</sub>	<b>4.40</b>	3.00
	171.78 SF	0.00	9.68	116.81
Seal/prime more than the floor perimeter -	125.50 SF	9,00	9.37	16,44
Paint the walla - trie coat	30 <b>8.00 SF</b>	0.00	0,40	123,20
Basebourd - 2 1/4"	11.83 LF	0.00	2,49	
Seal & paint baseboard - two coats	41.83 LF	0.00	0,99	104.16
Carpet	197.54 SF	0.00	3.03	41,41
15 % waste added for Carpes.	- 13 13 13 13 13 13 13 13 13 13 13 13 13		2.03	598.55
Carpet pind	171.78 SF	-8r <b>-9.00</b>	0.53	91.04
R&R Casing - 2 1/4"	17.00 LF	0.39	1.65	34.68
Scal & paint casing - two costs	17.00 LF	0.60	0.99	34.0 <b>8</b> 36.83
Detach & Reset Window blind - horizmust-	1,00 EA	0.00	9.00	35.51
Electrical	•			
R&R Dimmer switch - High grade	1.00 EA	3.91	50.29	54.20
R&R Outlet - High grade	4.00 EA	3.91	20.86	29.08
These need to be tamper resistant devices per the N	EC 2008 code.			77100
(Install) Hanging light fixture	1.00 EA	0.00	59.38	59.38
CODE			,	57.54
110 volt copper wining rus 1/2"conduit 151f box/plug/switch	1.00 EA	<b>0.00</b> (c) (c)	118.53	118.53
R&R #14 to #16 gauge copper wire - tranded or solid	150.00 LF	0.34	0.75	163.50
Totale: Dining Room				5,138.94

45669-ESCOBAR-CODE

7/8/2009

Page: 15

WE 12/43

2/21/0989 13:11 1 /153448783

### **D** UNIVERSAL Universal Restoration Services

20 Holbrook Drive Vheeling, IL 60090 Phone (888) 877-6766 Fix (888) 596-4998

1-20-II	174.67 SF Walls		29.71 SF Ceiling	
See 5. 12	104.38 SF Walts & Cei	ling	19.71 SF Floor	
Herri	3.30 SY Flooring		21.83 LF Floor Peri	meter
(Inches)	11.93 LF Ceil. Perime	le <del>s</del>		
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
78° drywall shing, taped, floated, ready or paint	29.71 SF	0.00	1 64	48.72
/2" drywall - hurig, taped, floated, rendy or paint	174.67 SF	0.00	1.54	168.99
Ilean floor underlayment	29.71 SF	9.00	3.32	9.51
Seal underlayment for odor control	29.71 SF	0.00	0.41	12.18
Team stud wall	174.67 SF	0.00	0.56	97 82
Ecal stud wall for odor control	174.67 SF	<b>0.00</b>	0.61	106.55
Seal floor or ceiling joist systems	29.71 SF	0.00	0.73	21.69
cal/prime the walls and ceiling - one coat	204.37 SF	0.00	0.37	75.62
&R Vanity	5.17 LF	5.84	129.85	701.51
/anity top - Detach and reset	5.17 LF	0.00	15.00	77.55
Saxeboard - 2 1/4"	16.67 LF	t). <b>00</b>	2.49	41.51
Backsplash - solid surface - Unastached - Detach & reset	3.00 LF	0.00	1.13	9.99
tase shoe	10.0 <b>0 LF</b>	0.00	1,24	12,40
seal & paint baseboard w/cap &/or shoe -	204.37 LP	0.00	1.18	241.16
Detach & Reset Towel bar	1.00 EA	0.00	9.00	17.46
Ceramic tile	29.71 SP	0.00	10.61	315.22
R&R Interior door unit	1.00 EA	14,59	141.64	156.23
eint door slab only - 1 cost (per side)	1.00 EA	0.00	14.19	56.76
Detach & Reset Door dummy knob =	1.00 EA	0.00	0.00	3.29
R&R Casing - 2 1/4"	17.0 <b>0 LIF</b>	0.39	1.65	34.68
Scat & paint casing - two coats	17.0 <b>0 LF</b>	0.00	0.99	16.83
sint door or window opening - 1 cost (per ide)	2,00 EA	0.00	14.51	29.02
Hectrical				
L&R Ground fault interrupter (GFI) outlet	1.00 EA	3.51	28.35	31.36
69-ESCOBAR-CODE			7/8/2009	Pager

.3153448783

1374**3** 

### UNIVERSAL

### Universal Restoration Services

) 90 Halbrook Drive Vheeling, IC 60090 Phone (888) 877-6766 Fix (388) 595-4996

A.C.

# CONTINUED - Bank

DESCRIPTION	QNEY	REMOVE	REPLACE	COTAL
Z&R Switch	2.00 EA	3.91	15.46	38.74
Install) Light bar • 2 lights	1.00 EA	0.00	51.82	51.82
R. Bathroom ventilation fan	1.00 EA	13,70	89.44	103.14
Rat R #14 to #16 gauge copper wire - irranded or solid	10.00 LF	0.34	9.75	78,10
Plumbing			\$2	
Detach & Reset Sink - single	1.00 EA	0.00	0,00	160.14
Install) Sink strainer and drain assembly	1.00 EA	ა <b>ე</b> ე	33.39	33.59
Detach & Reset Sink faucet - Bathroom	1.00 EA	0.00	9.00	128.43
Detach & Reset Toiles	1.0 <b>0 EA</b>	0.00	0.00	257.81
Yotals: Bath				3.263.12

THE STATE OF THE S		Family Root	*		Ceill	og Height: 8'
			317.83 SF Walls		360.35 SF Ceiling	
			578.18 SF Walls & Ceiling		260.35 SF Floor	
			28.93 SY Flooring		12.33 LF Floor Peri	werer
			51.92 LF Ceil. Perimeter			
Missing Walls	1-	3'8" X 4"7"	Opens into Exterior		Goes to neither Floor	/Ceillog
Missing Walls	ı.	3'8" X 4'7"	Opens into Exterior		Goes to neither Floor	-
Missing Wall:	1-	13'7" X \$'6"	Opens into Exterior		Goes to Floor/Ceiling	
Missing Walls	1-	3'7" X 6'8"	Opens iato Exterior		Goes to Floor	•
DESCRIPTION	**.		QNTŸ	REMOVE	REPLACE	TOTAL
5/8" drywail - hun for paint	g, iaped,	, floated, ready	360.35 SF	0.00	1.64	426.97
1/2" drywail - hun for paint	g, taped,	, floated, ready	31 <b>7.83 SF</b>	0.0 <b>0</b>	1.54	489,46
Clean floor wateri	ayment		26 <b>0.35 SF</b>	9.00	0.32	33.31
Seal underlayment	for ode	r control	260.35 SF	0.00	0.41	106.74
Clean stud wail			3 [7.83 SF	0.00	0.5 <b>6</b>	177.98
Scal stud wall for	odor con	trol	317.83 SF	0.00		193.88
Seal floor or ceilin	g joist s	ystem	250.35 SF	0.00	0.73	120.06
15669-ESCOBAR-C	BGO				7/8/2009	Pages 17

.3/21/7009 10:11 13153440783

马服 19/48

### Universal Restoration Services

1:0 Holbrook Drive Wheeling, IL 50090 Phone (888) 877-6756 Fax (888) 596-4996

### CONTINUED - Family Room

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Seal then paint the ceiling (2 coats).	250,35 SF	9.00	9,68	177 04
Scal/prime more than the floor perimeter -	211.67 SF	o <b>oo</b>	9.37	78.32
Saint the walls - one cost	317.83 SF	9.00	0.40	127.13
Base insulation - 4" - R13	153.33 SF	0.00	V.58	38.93
Paint door or window opening - 1 coat (per side)	2.00 EA	0 00	11.51	79.02
3olustrade	9.58 LF	0.00	114,29	1,094,90
itain & linish balustrade	9.58 LF	0.00	20.70	198.31
Paseboard - 2 1/4"	42.33 LF	0.00	2.49	105,40
Seal & paint baseboard - two coats	42.33 LF	0.00	ð.9 <b>9</b>	48.91
Carpet	299.40 SF	0.0 <b>0</b>	3.03	-07.18
5 % waste added for Carpet.				
Carpet pad	260.35 SF	9.00	0.53	137,99
Electrical				
ReR Outlet - High grade	5.00 EA	3.91	20.86	148.62
These need to be tamper resistant devices per the	NEC 2008 code.			
LER Switch	1.00 EA	J.91	15.46	19.37
R&R #14 to #16 gauge copper wire -	210.00 LF	0.34	0.75	228,90
Totals: Family Room				5,0 <b>51.42</b>



Hallway

84.00 SF Walls 101.22 SF Walls & Coiling

1.91 SY Flooring 10.50 LF Ceil. Perimeter

Ceiling Height: 8! 17.22 SF Ceiling

17.22 SF Floor 10.50 LF Floor Perimeter

		3'4" X <b>8'0"</b> 3'4" X 8'0"	Opens into Exterior Opens into Exterior		Goes to Floor/Ceiling Goes to Floor/Ceiling	
DESCRIPTION			QNTY	REMOVE	REPLACE	TOTAL
5/8" drywall - hun for paint	g, taped	, floated, ready	17.22 SF	9.00	1.64	28.24

45669-ESCOBAR-CODE

7/8/2009

Page: 18

57.217.2009 13:11

.3153448783

NE 19749

## Universal Restoration Services

90 Holbrook Drive Vheeling, IL 60090 hone (883) 877-6766

iux (888) 596-4996

### CONTINUED - Hallway

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
R&R 1/2" drywall - hung, taped, floated,	34.00 SF	0.33	1.54	157,08
Clean floor underlayment	17.22 SF	0.00	1.32	5.51
Seal underlayment for odor control	17.22 SF	0.00	0.41	7.06
Clean stud wall	34.00 SF	0.00	0.56	47 04
Scal and wall for odor control	4.00 SF	0.00	0.61	\$1.24
Scal floor or ceiling joist system	17.22 SF	2.00	0.73	12.57
Seal then paint the ceiling (2 coats)	17.22 SF	J <b>30</b>	0.68	11.71
Scal/prime more than the floor perimeter - ne coat	52.50 SF	0.00	0.37	19.43
Paint the walls - one coat	34.00 SF	0.00	0.40	13.60
Baseboard - 2 1/4"	10.50 LF	0.00	2,49	26.13
Scal & paint baseboard - two coats	10.50 LF	0,00	0.99	10.40
Carpet	19.81 SF	9.00	3.03	50.02
15 % waste added for Carpet.			· · · · · · · · · · · · · · · · · · ·	
Carpet pad	17.22 SF	Ú. <b>ÚO</b>	9.53	9.13
RAR Casing - 2 1/4"	17.00 LF	0.39	1.65	34.68
Seal & paint casing - two coats	17.00 LF	0.00	0.99	16.83
Detach & Reset Window blind - horizontal er vertical - Large	1.00 EA	0.00	0.00	35.51
P&R Bifold door - Colonist - Single	1.00 EA	<b>7.72</b>	125.12	134.84
Paint single bifold door - slab only - 2 coats per side)	2.00 EA	ა.00	21.07	12.14
Totals: Hallway		1		743.18



Claset

Coiling Height: 8'

108.00 SF Walls 118.63 SF Walls & Cailing

1.18 SY Flooring 13.50 LF Ceil Perimeter 10.63 SF Ceiling 10.63 SF Floor

13.50 LF Floor Perimeter

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
5/8" drywall - hung & fire taped only	10.63 SF	9.00	1.28	13.61
15669-ESCOBAR-CODE			7/8/2009	Page: 19

S-9E 01740



## Universal Restoration Services

70 Holbrook Drive Vheeling, IL 50090 Phone (388) 877-5766 Fax (888) 596-4996

### CONTINUED - Closet

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
1/2" thywall - hung, taped, floated, ready for paint	10 <b>8.00 SF</b>	0.00	1.54	160.32
Clean floor underlayment	10.63 SP	0.00	0.32	3.40
Scal underlayment for odor control	10. <b>63 SF</b>	0.00	0.41	4.36
Clean stud wal)	198.00 SF	0.00	0.56	60.48
esi sud wali for odor control	108.00 SF	9.00	0.61	o <b>5.38</b>
Scal floor or ceiling joist system	10.63 SF	<b>00.</b> 6	0.73	7.76
Ival then paint the walls and ceiling (2 coats)	118.63 SF	9.00	0.68	30,67
Baschourd + 2 1/4*	13.50 LF	9.90	2,49	33.62
Seal & paint baseboard - two coats	13.50 LF	0.00	0.99	13.37
Curpet	12.22 SF	90,0	3.03	37.03
5 % waste added for Carpet.				
Carper ped	10.63 SF	9.00	0.53	5.63
R&R-Bifold door - Colonist - Single			125,12	134,84
Paint single bifold door - slab only - 2 coats per side)	2.00 EA	. 2.0 <b>0</b>	11.07	12.14
R&R Casing - 2 1/4"	17.00 LF	0.39	1.6 <b>5</b>	34.68
Scal & paint easing - two coats	17 00 LF	3.00	0.99	16.83
Detach & Reset Window blind - horizontal or vertical - Large	1.00 EA	9.00	0.00	33.51
Totals: Closes				756.13
Total: First Floor				31,675.06

### Second Floor

7 1*	Landing		Ceiting Height: 12' 16"
		216.08 SF Walls	26.17 SF Ceiling
lamana v 50		242.25 SF Walts & Ceiling	26.17 SF Floor
1-30-1-3+11		2.91 SY Flooring	17.83 LF Floor Perimeter
		17.83 LF Ceil, Perimeter	
Missing Wall: 1 -	3.04 X 13.104	Opens into State2	Goes to Floor/Ceiling

45669-ESCOBAR-CODB

7/8/2009

Page: 20

3/01/2089 13:11

13153448793

wiE 12/10

### CHIVERSAL

### Universal Restoration Services

200 Holbrook Drive Wheeling, IL 60090 Phone (888) 877-6766 Pax (888) 596-4996

### CONTINUED - Landing

	A Arthur Control			
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
5/8" drywall - hung, taped, floated, ready for paint	26.17 SF	0.00	1.64	12.92
1/2" drywall - hung, tsped, floated, ready for paint	216.08 SF	9.00	1,54	332.76
R&R Batt insulation • 4" - R13	113.00 SF	0.28	0.58	27.18
Scal/prime the walls and ceiling - one coat	242.25 SF	0.00	0.37	39.63
Paint the walls and ceiling - one coat	24 <b>2.25 SF</b>	<sup>2</sup> ⇒ 0.00	0,40	96.90
R&R Underlayment = 1/4 BC plywood	26.17 SF	1.02	1.33	11.50
Carpet	50.09 SF	0.00	3.03	91.17
15 % waste added for Carpes,		Ya suja	-,,,	, <b>, , , ,</b>
Carper pad	26.17 SF	0.00	0.53	13.87
Baseboard - 2 1/4"	17.83 L.P	0.00	2.49	44,40
Sent & paint baseboard - two cours	17.83 LF	0.00	0.99	17.65
Totals: Landing				5 <b>87.98</b>



Stairt

Criting Height: 17\*

224.00 SF Walls & Ceiling 5.91 SY Flooring 16.00 LF Ceil, Perimeter

53.23 SF Floor 24.08 LF Floor Perimeter

24.00 SF Celling

Missing Wall: 1 - 3'0" X 17'0"	Opens into Exterior	,	Gues to Floor/Ceillog	
DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
5/8" drywall - hung, taped, floated, ready for paint	24.00 SF	9.00	1.64	39.36
1/2" drywall - hung, uped, floated, ready for point	20 <b>0.00 SF</b>	0.00	1.54	308.00
R&R Underlayment - 1/4" BC plywood	53.23 SF	1.02	1.33	125.09
Scal/prime the walls and criting - one coat	224.00 SF	0.00	9.37	82.8 <b>8</b>
Paint the walls and ceiling - one cost	224.00 SF	0.00	9.4 <b>0</b>	8 <b>9.60</b>
Сигрев	61.22.SF	0.00	3.03	185.50
15 % waste added for Curpet.				
Carpot pad	53.23 SF	0.00	0.53	28.21
45669-ESCOBAR-CODE			7/8/2009	Pager 21

B/C1/C089 13:11

13153448783

VE 2743



### Universal Restoration Services

190 Holbrook Drive Theeling, IL 60090 Phone (888) 877-6766 Fax (888) 596-4996

### CONTINUED - Stairt

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Totals: Stair)				358.64



•		٠.	•	
٦	18	111	7	

Ceiling Height: 17'

231.83 SF Walls 231.83 SF Walls & Ceiling 5.89 SY Flooring 18.67 LF Ceil, Perimeter 23.50 SF Ceiling 52.98 SF Floor 24.37 LF Floor Perimeter

Missing Wall: 1 - 3'8" X 17'0"	Opens into Landing		Gees to Floor/Critis	
DESCRIPTION	QNTY	REMOVE	EMOVE REPLACE	
5/8" drywall - hung, taped, floated, ready for paint.	23.50 SF	9,00	1.64	13,54
1/2" drywall - hung, taped, floated, ready for paint	208.33 SF	0.00	1,54	320.83
R Underlayment - 1/4" BC plywood	5 <b>2.98 SF</b>	1.02	1.33	124.50
Scal/prime the walls and ceiling - one coat	231.83 SF	9.00	9,37	35.78
Paint the walls and ceiling - one coat	231.8 <b>3</b> SF	0.00	0.40	92.73
Carpet	60.93 SF	0.0 <b>0</b>	3.03	184.62
15 % waste added for Carpet.				
Carpet pad	5 <b>2.98 SF</b>	0.00	0.53	28.08
Totals: Stair2				375.08

13153448783

14年 121/49



### Universal Restoration Services

200 Holbrook Drive Wheeling, IL 60090 Phone (888) 877-6766 Fax (888) 596-4996

717		Muster Bed		s No	Ceili	lag Height: 8'
		507.67 SF Walls & Ceiling 27.78 SY Flooring 37.00 LF Ceil. Perimeter		249.98 SF Ceiling 249.98 SF Floor 56.25 LF Floor Perimeter		
Missing Wall:	1 -	4'3" X 6'8"	Opens into Closes		Goes ta Floor	
Missing Wallt	1 -	8'0" X 4'7"	Opens into Exteri		Gues to neither Floor	/Ceiling
Missing Walls	1 -	4.0 X 9.8	Opens into Exteri	-	Goes to Floor	
Mission Walls	1 -	2'6" X 6'8"	Opens Into MAST	ER BATH	Gues to Floor	
DESCRIPTION			QNEY	REMOVE	REPLACE	TOTAL
5/8" drywail - hun for paint	ig, taped,	floated, ready	249.98 SF	9.00	1.64	109.97
1/2" drywail - hun for paint	ig, tapod,	, floated, ready	30 <b>7.67 SF</b>	i). () <b>0</b>	1.54	731.81
R&R Underlayme	mt = 1/4"	BC plywood	249.9 <b>8 SP</b>	1,02	1.33	587.4 <b>5</b>
Scal/prime the wa	ils and co	ciling - one cost	75 <b>7.65 SF</b>	9. <b>00</b>	0.37	280.33
Paint the walls and	d cciling	- 000 coal	75 <b>7.65 SF</b>	0.00	0,40	303.06
R&R Interior doub pre-hung unit	ble door,	8' - Colonist -	1.00 EA	29.73	347.95	377.68
RAR Casing - 21	/4"		18.42 LF	0.39	1.65	37.57
Paint door or wine coats (per side)	luw open	ing - Large - 2	3.00 EA	0.00	25.28	75.84
Baseboard - 2 1/4	•		∂6.25 LF	9.00	2.49	154.96
Scal & paint baset	pourd - tv	vo coats	6 <b>6.25 LF</b>	0.00	0.99	55.59
Carpet			28 <b>7.48 SF</b>	<b>0.00</b>	3. <b>03</b>	371.0 <b>6</b>
15 % waste added	for Carp	iet,				
Carpet pad			249.98 SF	9.00	0.53	132,49
Paint door slab on	ly + I cos	at (per side)	8.00 EA	0.00	14.19	113.52
NOTE Paint door	two coat	t on each side, thi	s is a double door so this w	ill take 2 coats each	side x 2 doors.	
RAR Vanity			4.58 LF	5.84	129.85	6 <b>21.46</b>
Vanity top - Detac	h and re	set	4.58 LF	0.00	15.00	6 <b>8.70</b>
Backsplach - solid Detack & reses	<b>STREETS</b>	• Unamached •	3.0 <b>0 L.F</b>	0,00	3.33	9.99
Electrical						
R&R Outlet - High	h grade		6.00 EA	3.91	20.86	148.62
These need to be to	swibet te	sistant devices per	the NEC 2008 code.			
5669-ESCOBAR-C	ODE				7/8 <b>/2009</b>	Page: 21

13153449787

5 E 13/43



### Universal Restoration Services

190 Holbrook Drive Wheeling, (L 60090 Phone (888) 877-6766 Fax (888) 596-4996

### CONTINUED - Master Bed

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
tristall) Ceiling fan without light	1.90 EA	9.90	134.58	154.58
CODE				
110 volt copper wiring run and box * rough	1.00 EA	0.00	74 65	74.65
Smoke detector - High grade	1.00 EA	2.00	31.54	31.54
Totals: Master Bed				5,360.87

Y. at 5° -4	Closet	Ceiling Height: 8
7111	171.67 SF Walls	33.62 SF Ceiling
In relative marrie	105.28 SF Walls & Ceiling	33.62 SF Floor
17.	3.74 SY Flooring	20.75 LF Floor Perimeter
) = formatAll	25.00 LF Cml. Perimeter	

Missing Wall: 1 - 4'3" X 6'8"	Opens into Maste	r Bed	Goes to Floor	
DESCRIPTION	UNTY	REMOVE	REPLACE	TOTAL
5/8" drywail - huna. toped, floated, ready for paint	33. <b>62 SF</b>	0,00	1.64	55,14
1/2" drywail - hung, taped, floated, ready for paint	171.67 SF	0.00	1.54	264.37
Seal then paint the walls and ceiling (2 coats)	20 <b>5.28 SF</b>	0.00	0.68	139.59
R&R Underlayment - 1/4" BC plywood	3 <b>3.62 SF</b>	1.02	1.33	79.00
Baseboard - 2 1/4"	20.75 LF	0.00	2.49	51.67
Scal & paint baseboard - two coats	20.75 LF	0.0 <b>0</b>	0.99	20.54
Corpet	38.66 SF	<b>0.00</b>	3.03	117.14
15 % waste added for Carpet.				
Curpet pad	33.62 SF	0.00	0.53	17.32
Paint door slab only - 1 coat (per side)	8.00 EA	0.00	14.19	113.52
NOTE Paint door two coats on each side, this i	s a double door so this w	rill take 2 costs each s	ide x 2 doors.	
Closet Organizer - Melamine or Wire - Detach & reset	16.00 LF	<b>00.</b>	51.48	983.68
Electrical				
(Install) Light fixture	1.00 EA	9.00	38.17	38.17
669-ESCOBAR-CODE			7/8/2009	Page: 2

12/01/2009 13:11

13153448783

ME 03/40

### UNIVERSAL

### Universal Restoration Services

30 Holbrook Drive Theeling, IL 60090 hone (888) 877-6766 Fux (888) 596-4996

#### CONTINUED - Closes

DESCRIPTION Totals: Closet

ONTY

REMOVE

REPLACE

TOTAL 30.64

Ceiling Helght: 8'

**Humbing** 

45669-ESCOBAR-CODE

3athroom

179.33 SP Walls

210.81 SF Walls & Ceiling 3.50 SY Flooring 14.50 LF Ceil, Perimeter

31 47 SF Floor

31 47 SF Ceiling

22.00 LF Floor Perimeter

7/3/2009

Page: 25

Missing Wall: ! -2'6" X 6'8" Opens into Muster Bed Gues to Floor DESCRIPTION ONTY REMOVE REPLACE JATOI 5'8" drywail - hung, taped, floated, ready 31.47 SF 0.00 51.61 for paint 1/2" drywall - bung, topod, floated, ready-179.33 SF-0.00 1.54 276.17 for paint 5/8" drywail - hung, taped, floated, ready 31.47 SF 0.00 1.64 51.61 tor paint 1/2" drywail - hung, taped, floated, ready 179.33 SP 0.00 1.54 275.17 for paint Scal then paint the walls and ceiling (2 210.81 SF 9.00 0.68 143.35 coata) R&R Underlayment - 1/4" BC plywood 31.47 SF 1.02 1.33 73.96 Baseboard - 2 1/4" 22.00 LF 9.00 2.49 54.78 Scal & paint baseboard w/cap &/or shoe -210.81 LF 0.00 1.18 248.76 WO COALS A&R Interior door unit 1 00 EA 14.59 141.64 156,23 4.00 EA Paint door slab only - I cost (per side) 0.00 14.19 56.76 Detach & Reset Door dummy knob -1.00 EA 9.00 0.00 3.29 nerior R&R Casing - 2 1/4" 17.00 LF 9.39 1.65 34.68 Soal & paint casing - two coats 17.00 LF 0,00 0.99 16.83 Paint door or window opening - 2 coats 2.00 EA OO.C 21.49 42.98 per side) Electrical (Install) Light fixture 1.00 EA 9.00 38.17 38.17

4/21/2009 13:11

13153448793

0 4 37/48

### - UNIVEREAL

## Universal Restoration Services

190 Holbrook Drive Vheeling, IL 60090 Phone (888) 877-6766 Fax (888) 596-4996

## CONTINUED - Bathroom

ESCRIPTION	QNTY.	REMOVE	REPLACE	COTAL
Octaon & Reset Sink - single	1.00 EA	0.00	9.00	160.14
Install) Sink strainer and drain assembly	1.00 EA	9.00	33.39	33,39
Detach & Reset Toilet	1.00 EA	0.00	0.00	257.81
Detach de Reset Sink faucet - Bothroom	1.00 EA	2.00	3.0 <b>0</b>	123.43

Red Room

Celling Height: 8'



33.5.33 SF Walls & Ceiling 155.33 SF Walls & Ceiling

14.00 LF Ceil, Perimeter

120.00 SF Ceiling 120.00 SF Floor

41.50 LF Floor Perimeter

Missing Walk 1 - 2'6" X 6'8"	Opens into Exterior		Goes to Floor	
DESCRIPTION	QNTY	REMOVE	REPLACE	POTAL
5.8" drywall - hung, taped, floated, ready for paint	120.00 SF	0.00	1.64	196.80
1/2" drywall - hung, taped, floated, ready for paint	33 <b>5.33</b> SF	0.00	1.54	516.41
Seal then paint the walls and ceiling (2 coats)	455.33 SF	9.00	<b>0.68</b>	30 <b>9.62</b>
Baseboard - 2 1/4"	41.50 LF	9.00	2.49	103.34
Scal & paint baseboard - two coats	41.50 LF	0.00	0.99	41.09
R&R Undertayment - 1/4" BC plywood	120.00 SF	1.02	1.33	282.00
Curpet	138.00 SF	9.00	3.0 <b>3</b>	418.14
15 % waste added for Carpes.				
Carpet pad	120.00 SF	<b>2.00</b>	0.53	53.60
Electrical				
R&R Outlet - High grade	3.00 EA	3.91	20,86	74.31
These need to be tamper revistant devices per d	ne NEC 2008 code.			
(Install) Ceiling fan without light	1.00 EA	<b>0.00</b>	154.58	154.58
Install) Light fixture	1.00 EA	9.00	38.17	38.17
CODE	the spirit			
669-ESCOBAR-CODE			*/9/2009	Pager 2

8/21/2009 13:11

13152446783

) E 19749



## Universal Restoration Services

190 Holbrook Drive Wheeling, IL 60090 hone (888) 877-6766 inx (888) 596-4996

## CONTINUED - Bed Room2

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
110 volt copper wiring run and box - rough a culy	1.00 EA	9.0 <b>0</b>	74.65	*4.65
Smoke detector - High grade	1.00 EA	9.00	31,54	31.54
Totals: Bod Room2				3 354 35

	Bed room i		j Celling Height: 8'
100		142.00 SF Walls	125.00 SF Ceiling
		167.00 SF Walls & Criling	125.00 SF Floor
		13.89 SY Flooring	42.33 LF Floor Perimeter
P. C. S.		14.83 LF Ceil. Perimeter	
Masing Wall: 1-	2'6" X 6'8"	Opens into Exterior	Gues to Floor
	Subroom 2:	Closes2	Ceiling Height: 8'
		160.00 SF Walls	13.89 SF Ceiling
		173.89 SF Walls & Ceiling	13.89 SF Floor
المستعددة المستعدد		I SA SY Flooring	30 00 1 F Ft

	Subroom 2: Closes2	Ceiling Height: 8'
Tod Dame	1.54 SY F	Valls & 13.89 SF Ceiling Valls & Ceiling 13.89 SF Floor

Subroom (	Closet !		Cei	uag Height: 8'
	160.00 SF Walls 173.89 SF Walls & Ceil 1.54 SY Flooring 20.00 LF Ceil, Perime	-	13.89 SF Cailing 13.89 SF Floor 20.00 LF Floor Per	rimeter
DESCRIPTION	QNTY	REMOVE	REPLACE	lotal.
5/8" drywail - hung, taped, floated, ready for paint	152.78 SF	9.0 <b>0</b>	1.64	250.56
1/2" drywaii - hung, taped, floated, ready for paint	662.00 SF	0,00	1.54	1,019,48

	.4	.001.10.0	WELL THAT IS	IUIAL
5/8" drywnii - hung, taped, Hooted, ready for paint	152.78 SF	0.00	1.64	250.56
1/2" drywail - hung, taped, floated, ready for paint	662.00 SF	0.00	1.54	1,019,48
Seal then paint the walls and ceiling (2 coars)	314.78 SF	<b>0.00</b>	0.68	554. <b>05</b>
\$5669-ESCOBAR-CODE			7/8/2009	Paget 27

ar 21/0099 13:11

13153449793

三三年 (2/4)

## UNIVERSAL.

## Universal Restoration Services

190 Holbrook Drive Wheeling, IL 60090 Phone (888) 377-6766 Fax (888) 596-4996

## CONTINUED - Bed room I

DESCRIPTION	ŲΝΤΥ	REMOVE	REPLACE	COTAL
Haseboard + 2 1/4"	32.33 LF	3.00	2.49	105.00
leat de paint baseboard - two coats	82.33 LF	<b>9.00</b>	9.9 <b>9</b>	31,51
R&R Underlayment + 1/4" BC plywood	152.78 SF	1.02	1.33	359.04
Carpet	175.69 SF	9.0 <b>0</b>	3.03	512.54
15 % waste added for Curpet.				
Curpet pad	:52.78 SF	9 0 <b>0</b>	9,53	:0.97
Electrical				
P.&R Outlet - High grade	3.00 EA	3.91	20.86	74.31
These need to be tamper resistant devices per the	NEC 2008 code.			
Install) Ceiling fon without light	1.00 EA	0.00	154.58	154,58
(Install) Light fixture	1 00 EA	0.00	38,17	78.17
CODE				
110 volt copper wiring run and box - rough in only	1.00 EA	0.00	74.65	74.65
Smoke detector - High grade	1.00 EA	0.00	31.54	81.54
Totala: Bed room I	:			1,506.20

ev-12**	r2* 3*	Hallway		Ceiling Height: A'
2 30 mm	3/4		147.44 SF Walls 202.44 SF Walls & Cailing 6.11 SY Flooring 24.33 LF Ceil Perimeter	55.00 SF Coiling 55.00 SF Floor 17.25 LF Floor Perimeter
:BaW gulasiW.	1.	3'8" X 6'8"	Opens into Exterior	Goes to Floor
Missing Wall:	1 -	6'0" X 8'0"	Opens into Exterior	Goes to Floor/Ceiling
Missing Wall:	1 -	2'6" X 6'8"	Opens into Exterior	Gues to Floor

.372172389 13:11

13153448783

· A 起 - 1, 37,43

## WINELEN

#### Universal Restoration Services

390 Holbrook Drive 'Vheeling, IL 60000

Wheeling, IL 60090 Phone (888) 877-6756 Pax (888) 596-4996

### CONTINUED - Hallway

inbroom I: Closet

Ceiling Height: 8'



62.78 SF Walls 67.53 SF Walls & Ceiling 9.53 SY Flooring

4.75 SF Ceiling 4.75 SF Floor

9.17 LF Ceil Perimeter

7.58 LF Floor Perimeter

**Hissing Walk** 1'7" X 6'8" Opens into Hallway Goes to Floor DESCRIPTION ONTY REMOVE REPLACE COTAL 5/8" drywail - hung, taped, floated, ready 59.75 SF 0.00 97,99 1.54 for paint 1/2" drywaii - hung, taped, floated, ready 210.22 SF 0.00 1.54 323.74 for paint Send then point the walls and ceiling (2 269.97 SF 0.00 9.68 183.58 train) Batt insulation - 6" - R19 59.75 SF 0.00 9.72 43.02 R&R Underlayment - 1/4" BC plywood 59.75 SF 1.02 1.33 140.42 Carpet 58.71 SF 0.00 3.03 208.19 15 % waste added for Carpet Curpet pad 59.75 SF 0.00 0.53 31.67 Baseboard - 2 1/4" 24.33 LF 0.00 2.49 61.83 Seal & paint baseboard w/cap &/or shoe -269.97 LF 0.00 1.18 318,56 two coats Detach & Reser Shelving - 12" - in place 15.83 LF 0.00 0.00 115.40 NOTE (5) five shelfs at 3 feet and 2 inches. CODE 0.00 74.65 74.65 110 voit copper wiring run and box - rough 1.00 EA in only Carbon monoxide detector - High grade 1.00 EA 0.00 92.57 92.57

45669-ESCOBAR-CODE

Totals: Hallway

7/3/2009

Page: 29

1.591.62

3/31/2009 13:11

13153449793

THE 31/41



## Universal Restoration Services

190 Holbrook Drive Viceting, IL 60090 Thone (888) 877-6766 fax (888) 596-4996



Spare Hath

Criting Height: 8'

239.67 SF Walls & Ceiling 5.15 SY Flooring 5.23 LF Ceil, Perimeter

55.33 SF Ceiling 55.33 SF Floor 29.83 LF Floor Perimeter

DESCRIPTION ONTY REMOVE REPLACE TOTAL 5.8" drywnil - hung, isped, floated, ready 55.33 SF 0.00 1.54 **VO.74** for paint 1/2" drywall - hung, toped, floated, ready 238.67 SF 0.00 1.54 367.55 for paint Batt insulation - 6" - R19 55.33 SF 0.00 0.7219.84 Scal then paint the walls and ceiling (2 294.00 SF 0,00 0.68 199.92 (espo: Mirror - 1/4" plate glass 30.00 SP 0.00 10.83 324.90 Vanity 5.08 LF 9.00 129.85 559.64 1/2" Cement board 50.00 SF 0.00 3.46 207.60 Tile tub surround - up to 60 SF 1.00 EA 0.00 914.33 714.33 Rathrub - Standard grade 1.00 EA 0.00701.02 701.02 Toilet - Standard grade 1.00 EA 0.00 329.37 329.37 Towel bar 1.00 EA 0.00 24.81 24.81 Towel ring 1.00 EA 0.0028.61 28.61 R&R Vinyl tile 55.33 SF 0.89 3.15 223.53 Baseboard - 2 1/4" 16.00 LF 0.00 2.49 39.84 Seal & paint baseboard w/cap dt/or shoe -294.00 LF 0.00 1.18 346.92 TWO COMES R&R Interior door unit 1.00 EA 14.59 141.64 156.23 Paint door slab only - 1 coas (per side) 4.00 EA 0.00 14.19 56.76 Detach de Reset Door duramy knob -1.00 EA 9.00 0.00 3.29 interior 17.00 LF 0.39 R&R Casing - 2 1/4" 1.65 34.68 Scal & paint casing - two coats 17.00 LF 0.00 . 0.99 16.83 Paint door or window opening - 2 costs 2.00 EA 0.00 21.49 42,98 (per side) R&R Underlayment - 1/4" BC plywood 5**5.33 SF** 1.02 1.33 130.03 Plambing Detach & Reset Sink - single 2.00 EA 0.00 0.00 320.28 15669-ESCOBAR-CODE 7/8/2009 Page: 30

.3/21/2009 13:11

13153448783

THEE (12/48)

## LYIVERSAL

## Universal Restoration Services

30 Holbrook Drive Theeling, (L 50090 Thone (888) 377-6766 Fax (888) 596-4996

### CONTINUED - Spare Bath

DESCRIPTION	ONTY	REMOVE	REPLACE	FOTAL
Install) Sink strainer and drain assembly	2.00 KA	0.00	13,39	>5.78
Detach & Reset Sink faucet - Bathroom	2.00 EA	0.00	9.00	256.86
Demch & Reset Toilet	1.60 EA	0.00	0.00	257,81
CODE				
110 voit copper wiring run 1/2"conduit 151f box/plug/switch	1.00 EA	0.00	118.53	118.53
Ground fault interrupter (GFI) outlet	1.00 EA	0.00	.:8.35	28.35
Need to add a GFCI outlet per inspector because if	iere are two sinks in this	bathroom.		
Totals: Spare Bath				5.293.03

### General Conditions

UESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Dumpster loud - Approx. 20 yards, 4 tons of debris	1.00 EA	52 <b>3.31</b>	9.00	523.31
Cleaning Technician - per hour	18.00 FUR	0.00	29.71	534.78
NOTE Post construction clean up.				
Totals: General Conditions				1.058.09

### PERMIT

DESCRIPTION	QNTY	REMOVE	REPLACE	TOTAL
Taxes, insurance, permits & fees (Bid item)	1.00 EA	9.00	935.73	93 <b>5.73</b>
Totals: PERMIT				735.73
Total: Second Floor				27,512.25
Line Item Totals: 45469-ESCOBAR-CODE			ph management and the second	3.337.87

45669-ESCOBAR-CODE

7/3/2009

## 1320120739rmg D00c15至06月1edFols的10135/1至nteFenters的10135/13513至9:05xhi局ik性以时的t AP9中4月31日8日1

13/21/2009 13:11

1.0153448793

1 E 3740

### - UNIVERSAL

## Universal Restoration Services

190 Holbrook Drive Wheeling, IL, 60090 Phone (888) 877-6766 Eax (888) 596-4996

### Grand Total Areas:

5,907,24 SF Walls 2,427,63 SF Floor

0.00 SF Long Wall

2,427.63 Floor Area

NJ49,46 Exterior Wall Area

7.00 Surface Area 9.00 Total Ridge Length 1.283.95 SF Ceiling

269.74 SY Flooring 2.00 SF Short Wall

.

2.564.28 Total Area 760.17 Exterior Perimeter of Walls

0.00 Number of Squares 0.00 Total Hip Length 9,191.19 SF Walls and Ceiling

359.30 LF Floor Perimeter 393.25 LF Ceil. Perimeter

(93.23 LF Cell Penmeum

5,964.82 Interior Wall Area

0.00 Total Perimeter Length

45669-ESCOBAR-CODE

7'8/2009

29/11/2009 19:11

13153444793

5選 3474計



## Universal Restoration Services

170 Holbrook Drive Vheeting, IL 60090 Phone (888) 877-6766 Fux (888) 596-4996

٧.	ŧŧ	m	m	9	rv.

Une Item Total Maurial Sales Tax	<b>3</b>	9.250% x	3 <b>0,676.45</b>	:3.337.87 2.337.57
Subtomi				41,175,44
Overhead	<b>4</b>	10.0% x	91,175.44	2,117,54
Profit	્યુ	10.0% x	91,175.44	9.117.54
Replacement Cost Value			• •	7109,410.52
Net Claim			<i>i</i>	7109,410.52

Brian Bavero

45669-ESCOBAR-CODE

7/3/2009

37/217/2009 13:11 13153448793

- 15/4∂

## Onversal Universal Restoration Services

270 Holbrook Drive Wheeling, IL 60090 Phone (888) 877-6766 Fix (888) 596-4996

### Recap by Room

Estimate:	45669.	FSCORA	RACONE.

Garage Crawl Crawl Crawl Stage Laundry Room Laundry Room Basement Sta Laundry Room Basement Sta Laundry Room Laundry Room Laundry Room Basement Sta Laundry Room Laundry Room Laundry Room Basement Sta Laundry Laundry Laundry Laundry Basement Sta Laundry Stage First Floor Stage	Lrent	Hasement		
Furnace RM Laundry Room Laundry Room Jasement Jazzison Ja			*.495. <b>03</b>	3.48%
Laundry Room			3 <b>5.49</b>	9.96%
Savement   3,235,01   3,66%     Savement   1,130,78   1,236     Landing   519,43   0,59%     Area Subtutal: Basement   29,150,56   23,00%     Area Subtutal: Basement   42,14   0,59%     Landing   1,649,35   1,377%     Stale   2,22   2,85%     Front foyer   1,252,79   2,51%     Kitchen   1,650,77   13,19%     Stale   3,260,12   3,69%     Family Roome   5,158,94   5,32%     Sath   3,260,12   3,69%     Family Roome   5,051,42   5,72%     Hallway   713,18   2,84%     Closet   3,650,60   3,586%     Area Subtutal: First Floor   31,675,06   35,86%     Area Second Floor   3,675,08   3,99%     Master Bed   5,360,47   6,07%     Closet   1,380,64   2,13%     Bathroom   2,110,12   2,39%     Bed Room2   2,354,25   1,67%     Bed Room2   2,354,25   1,67%     Bed Room2   3,506,20   3,97%     Hallway   1,691,62   1,91%     Spare Bath   5,993,03   5,78%     Covery Conditions   1,058,09   1,20%     PERMIT   935,73   1,06%     Subtotal of Areas   38,137,87   190,00%			12,095.71	13.69%
Basement Sta			4.619.11	5.23%
Landing \$19.43 0.59%  Area Subtutal: Basement 29,150.56 23,00%  Vera: First Floor Stale 42,14 0.59% Landing 1,649.35 1.37% Stule2 55.4.22 1.85% Front foyer 2,225,79 1.53% Kiteben 11,659.77 13,19% Diolog Room 5,138.94 5.32% Sath 3,263.12 3.69% Family Room 5,138.94 5.32% Islama 3,263.12 3.69% Family Room 1,051.42 5.72% Hallway 713.18 9.84% Clouet 556.13 2.86%  Area Subtotal: First Floor 31,475.06 35.86%  Area: Second Floor Landing 387.98 1.01% Shirl 358.64 0.97% Shirl 358.64 0.97% Master Bed 5,160.47 5,07% Clouet 3,560.47 5,07% Clouet 1,880.64 2.13% Baltroom 2,110.12 2.19% Bed Room2 1,150.12 2.19% Bed Room2 1,150.20 3.99% Hallway 1,691.62 1.91% Spare Bath 5,093.33 6.78% General 3,560.20 3.97% Hallway 1,691.62 1.91% Spare Bath 5,093.33 6.78% General 1,058.09 1,20% PERMIT 935.73 1.06%		******	3,235.01	3.66%
Area Subtotal: Basensent         29,150,56         23,00%           Creat: First Floor         3141         0,59%           Stair         442,14         0,59%           Landing         1,649,35         1,37%           Stuir2         754,22         2,85%           Front foyer         2,225,79         2,52%           Kiteben         11,659,77         13,19%           Dissign Roome         5,135,94         5,23%           Jath         3,263,12         3,69%           Family Rouse         1,051,42         5,72%           Hallway         15,18         2,84%           Clouset         756,13         3,86%           Area Subtotal: First Floor         31,675,06         35,86%           Area: Second Floor         31,475,06         35,86%           Area: Second Floor         36,04         0,97%           Stair2         375,08         0,99%           Master Bed         5,360,47         0,07%           Stair2         375,08         0,99%           Master Bed         5,360,47         0,07%           Glacet         1,880,64         2,13%           Bed room I         3,306,20         3,97% <t< th=""><th></th><th></th><th></th><th>1.28%</th></t<>				1.28%
Piras Floer	-	Landing	519.43	0.59%
Stale		Aren Subtutal: Basement	29,150,56	33.00%
Landing   1,649.35   1,37%   Stalir2   154.22   1,85%   Front foyer   2,225,79   2,52%   Kitchen   11,650,77   13,19%   1369.47   5,136.94   5,82%   3,263.12   3,69%   3,263.12   3,69%   3,263.12   3,69%   3,263.12   3,69%   3,263.12   3,69%   3,263.12   3,69%   3,263.12   3,69%   3,26%   3,	\res:	· · ·		
Stair   Second Floor   S4.22   J.85%			+42.14	0.50%
Front foyer  Kitchen  11,650,77  13,194  Diolog Room  31th  5,115,94  5,225,79  3,265,12  3,265,12  3,094  Family Room  5,051,42  5,725  Hallway  713,18  9,845  Closet  31,675,06  35,865  Area: Second Floer  Landian  5,051,42  5,725  Hallway  713,18  9,845  Area: Second Floer  Landian  387,98  1,01%  Stair2  375,08  399%  Master Beal  5,360,87  6,07%  Gloset  9,110,12  2,19%  Bathroom  1,101,12  2,19%  Bed Room2  1,154,25  1,29%  Bed Room2  1,154,25  1,57%  Bed Room2  1,1691,62  1,91%  Spare Bath  5,993,03  6,78%  General Conditions  1,058,09  PERMIT  9,35,73  1,06%  Subtotal of Areas  88,337,87  100,00%			1,649.35	1.37%
Xirchem			154.22	J.85%
Diolog Roome   \$138,94   \$32%   3263.12   3.69%   Family Roome   \$138,94   \$3.263.12   3.69%   Family Roome   \$1,051.42   5.72%   13.18   9.84%   Clouse   756.13   0.86%   Clouse   Clous				2.52%
Sata   3,263,12   3,69%     Fattily Roome   5,051,42   5,72%     Hallway   713,18   9,84%     Clouse   756,13   0,86%     Aren Subtotal: First Floor   31,675,06   35,86%     Aren: Second Floor     Landing   387,98   1,01%     Stair2   375,08   3,99%     Master Bed   5,360,87   5,07%     Closet   1,880,64   2,13%     Bathroom   2,110,12   2,39%     Bed Room2   2,154,25   2,57%     Bed Room2   2,154,25   2,57%     Bed room I   3,566,20   3,97%     Hatlway   1,691,62   1,91%     Spare Bath   5,993,03   5,78%     General Conditions   1,058,09   1,20%     PERMIT   935,73   1,06%     Area Subtotal of Areas   37,512,25   31,14%     Subtotal of Areas   37,512,25   31,				13.19%
Fathily Rooms 5,051,42 5,72% Hallway 713,18 9,84% Clouse 5,051,42 5,72% Hallway 713,18 9,84% Clouse 5,051,42 5,72% 1,561,13 9,84% Clouse 5,051,13 9,86% Area: Second Floor 31,675,06 35,86% Stair1 358,64 0,97% 5,141,2 358,64 0,97% 5,141,2 8,75,08 3,99% Masser Bed 5,360,87 5,07% Closes 1,880,64 2,13% Bathroom 2,110,12 2,39% Bed Room2 1,840,64 2,13% Bed room 1 2,110,12 2,39% Bed room 1 1,541,25 2,57% Bed room 1 1,541,25 2,57% Bed room 1 1,541,25 2,57% General Conditions 1,058,09 1,20% PERMIT 935,73 1,06% Area Subinital: Second Floor 27,512,25 31,14% Subtotal of Areas 38,137,87 190,00%		·		
Hallway   713.18   2.84%   Closet   756.13   2.86%   Closet   Cl			- 1 2 - 2 - 2	3.69%
Close			-	
Area Subtotal: First Floor 31,675.06 35.86%  Area: Second Floor  Landian 387.98 1.01% Stair1 358.64 0.97% Stair2 875.08 9.99% Master Bed 5,360.87 5.07% Closet 1.889.64 2.13% Bathroom 2,110.12 2.39% Bed Room2 2.154.25 2.57% Bed room 1 3.506.20 3.97% Hallway 1,691.62 1.91% Spare Bath 5,993.03 5.78% General Conditions 1.058.09 1.20% PERMIT 935.73 1.06%  Subtotal of Areas 38.137.87 190.00%				
Area: Second Floor  Landing	•		- 70.13	1.8 <b>4%</b>
Landing   387.98   1.01%   Stuir   358.64   0.97%   Stair   358.64   0.97%   Stair   358.64   0.97%   358.62   3.99%   Master Bed   5.360.87   5.07%   Closet   1.880.64   2.13%   Bathroom   2.110.12   2.39%   Bed Room   2.110.12   2.39%   Bed Room   2.154.25   2.57%   Bed room   1.354.25   2.57%   Bed room   1.560.20   3.97%   Hatiway   1.691.62   1.91%   Spare Bath   5.993.03   6.78%   General Conditions   1.058.09   1.20%   PERMIT   935.73   1.06%   Area Subtutair Second Floor   27,512.25   31.14%   Subtutair Second Floor   27,512.25   31.14%   Subtutair Second Floor   27,512.25   31.14%   Subtutair Of Areas   38,337.87   190.00%   Subtutair Second Floor   27,512.25   31.14%   Subtutair Of Areas   38,337.87   190.00%   Subtutair Second Floor   27,512.25   31.14%   Subtutair Of Areas   38,337.87   190.00%   Subtutair Second Floor   27,512.25   31.14%   Subtutair Of Areas   38,337.87   300.00%   32.337.87   300.00%   32.337.87   300.00%   32.337.87   300.00%   32.337.87   300.00%   32.337.87   300.00%   32.337.87   300.00%   32.337.87   300.00%   32.337.87   300.00%   32.337.87   300.00%   32.337.87   300.00%   32.337.87   300.00%   32.337.87   300.00%   32.337.87   32.337.		Area Subtotal: First Floor	31,675.06	35.86%
Stuir   358.64   0.97%   5tair 2   875.08   0.99%   Masser Bed   3.360.87   5.07%   Closet   1.880.64   2.13%   Bathroom   2.110.12   2.39%   Bed Room 2   2.354.25   2.57%   Bed room 1   3.506.20   3.97%   Hatiway   1.691.62   1.91%   Spure Bath   5.993.03   6.78%   General Conditions   1.058.09   1.20%   PERMIT   935.73   1.06%   Area Subtotal: Second Floor   27,512.25   31.14%   Subtotal of Areas   3.37.87   190.00%   1.00	Areat			
State   Stat				
Master Bed       5,360,87       5,07%         Closet       1,380,64       2,13%         Bathroom       2,110,12       2,39%         Bed Room2       1,254,25       2,57%         Bed room t       3,506,20       3,97%         Hattway       1,691,62       1,91%         Spare Bath       5,993,03       5,78%         General Conditions       1,058,09       1,20%         PERMIT       935,73       1,06%         Area Subtutal: Second Floor       27,512,25       31,14%         Subtutal of Areas       38,137,87       190,00%				
Closet		· · · · · -		
Bathroom   2,110,12   2,39%     Bed Room2   2,354,25   2,57%     Bed room I   3,506,20   3,97%     Hallway   1,691,62   1,91%     Spare Bath   5,993,03   6,78%     General Conditions   1,058,09   1,20%     PERMIT   935,73   1,06%     Area Subtutak Second Floor   27,512,25   31,14%     Subtutal of Areas   38,337,87   100,00%				
Bed Room2				
Bed room   3.506.20 3.97%   Hallway			· · · · · · · · · · · · · · · · · · ·	
Hallway				
Spare Bath   5,993.03   6,78%				
General Conditions   1,058,09   1,20%     PERMIT   935,73   1,06%     Area Subintal: Second Floor   27,512,25   31,14%     Subtotal of Areas   38,137,87   190,00%		The state of the s	**	
PERMIT         935.73         1.06%           Area Subtotal: Second Floor         27,512.25         31,14%           Subtotal of Areas         38,337.87         190,00%		• • • • • • • • • • • • • • • • • • • •		
Area Subtotal: Second Floor 27,512.25 31,14% Subtotal of Areas 88,337,87 190,00%				*
Subtotal of Areas 88,137,87 190,00%	•	LEKWII	935,73	1.06%
Oddyla) Provys		Area Subtutal: Second Floor	27,512.25	31.14%
5669-ESCOBAR-CODE 7.3/2009 Paget 34	Subtoti	if of Areas	38 <b>.337.87</b>	190,00%
	5669-E	SCOBAR-CODE	. 7,8/2 <b>009</b>	Page: 34

\_8/21/2009 13:11

19183448793

174億 (25740)

DINVERSAL Universal Restoration Services

"10 Holbrook Drive Wheeling, IL 50090 Thone (888) 877-6766 Pax (888) 596-4996

Total.

3.337.87

190.00%

2.8/2009

JE/01/0009 13:11 13153448783

小田 (274)

## . UNIVERSAL

## Universal Restoration Services

20 Holbrook Drive Vheeting, II. 60090 hone (888) 877-6766 fix (888) 596-4996

## Recap by Category

O&P Items	Total Dollars	24
\PPLIANCES	169,14	0.60%
CABINETRY	1,517,46	7.78%
CLEANING	2,322,35	1.58%
GENERAL DEMOLITION	3.877.72	1.54%
D <b>OORS</b>	1,743,35	1.59%
DRYWALL	13,778.55	12.59%
ELECTRICAL	5,928.67	5.42%
ELECTRICAL - SPECIAL SYSTEMS	1,946.09	1.69%
FLOOR COVERING - CARPET	5.334.06	5,79%
FLOOR COVERING - CERAMIC TILE	29 <b>7.60</b>	0.19%
FLOOR COVERING - VINYL	!.77 <b>7.72</b>	1.62%
PERMITS AND FEES	235.73	0.86%
FINISH CARPENTRY/TRIMWORK	5.723.5 <b>7</b>	5.23%
FINISH HARDWARE	175.55	J.16%
HEAT, VENT & AIR CONDITIONING	7,466.15	1.65%
INSULATION	1,093,05	1.00%
LIGHT FIXTURES	1,132.21	1.03%
MARBLE - CULTURED OR NATURAL	146.25	0.13%
MIRRORS & SHOWER DOORS	324.90	0.30%
PLUMBING	5,140.85	4.70%
PAINTING	12.029.00	10.99%
FILE	3,443,86	J.15%
WINDOW TREATMENT	142,04	0.13%
Subjetal	:4,337.87	30.74%
Material Sales Tax @ 9.250%	2,837.57	1.59%
Overhead @ 10.6%	9,117.54	1.33%
Profit <u>@</u> 10.0%	9,117.54	333%
O&P Items Subtorat	109,410.52	100,00%

# 1320120720 rmg Dec 15506 Filed Folgo 10/25/12 nte Fenters of 10/25/13:13:59:05 khi Fix Heighti Bit A POP 5040 5841


79/21/2009 13:11 13163448783






±Va£ = ±7/4∂








45mm-ESCUBAN CODE

Fust Floor



## **EXHIBIT B**

## 1520122780 mg Dec 15506 falled File of 1980 112/35/12 hte Ferters @ 112/0122780 mg Dec 15506 falled File of 1980 112/35/12 hte Ferters @ 152/0122780 mg Dec 15506 falled File of 1980 112/35/12 https://doi.org/10.1016/10.10

ANY QUESTIONS, CONTACT:

CLAIM SERVICES 25510 W.11 MILE RD SOUTHFIELD MI 48034 (877) 851-5721

30709708 DATE: 08-24-2009 AMOUNT: \$\*\*\*\*108,910.52 NON-NEGOTIABLE

CLAIM NO: 004010763

DATE OF LOSS: 05-10-2009

CLAIMANT: JORGE ESCOBAR PAYEE: JORGE ESCOBAR

IN PAY OF: FOR FIRE LOSS. 45669-ESCOBAR-CODE

COVERAGE DWELLING

PAY TYPE

REPLACEMENT COSTS

\$108,910.52

LOAN # 0601300779

RETAIN STUB FOR RECORDS

VERIFY THE AUTHENTICITY OF THIS MULTI-TONE SECURITY DOCUMENT. CLAÍN SERVICES 23570 W 11 MILE RD SOUTHFIELD MI 48034

CHECK BACKGROUND AREA CHANGES COLOR GRADUALLY FROM TOP TO BOTTOM AUTO CLUB INSURANCE ASSOCIATION MEMBERSELECT INSURANCE COMPANY

4-478

PAY TO THE ORDER OF

JORGE ESCOBAR & SINDY ESCOBAR

WHEELING IL 60090

NO. 30709708

\*\*\*\*108,910.52

VOID AFTER 180 DAYS

CLAIM NO: 004010763 DATE-OF-LOSS: 05-10-2009

COMERICA BANK & TRUST, NA

THE UBICINAL DUCKMENT HAS & MAILE DESI ENTINE MATERIARY UPLAN AND DISCUSSION EAT OF THE SARRY HIS

& GMAC MORTGAGE CORP, ISAGA & UNIVERSAL RESTORATION SERVICES 390 HOLBROOK DRIVE

ીવીઓજિનીકનીત્રીક્ષિતાની તેને જિલ્લાની તેની 🧭

## **EXHIBIT C**

IN THE CIRCUIT COURT OF COOK COUNTY, ILLING	aUI.	IN	T I	11 .	NTY	COU	COOK	T OF	THE CIRCUIT COUP	LEV
---	------	----	-----	------	-----	-----	------	------	------------------	-----

GMC Mortgage UC

No. 09 CH 7418

ORDER

control on on to Entervene, the notice having her give & the court kning buy advised in the premises;

It is HEREBY ORDERED THAT: Universal Restoration Serveres

Muhan to Interiore is withdrawn as (1) Universal Restaution Services
has received checks from AAA Insures for \$12,417.49 and \$39,270.01 for water
doinger repairs, and (3) all parties upon to enderse \$2,746.82 Check when this
for water Janog reports when their is issued, which stall then be turned over
to Universal Restriction Services; and (3) GMPC is receiving fully negotiable check
to Viveral Restriction Services; and (3) GMPC is receiving fully negotiable check
to Viveral Restriction Services; and (3) GMPC is receiving fully negotiable check
to Viveral Restriction Services; and (3) GMPC is receiving fully negotiable check

Acty. No.: 41750 for Slot, 91052 for portion of prospectice

Name: Kata Law Office (41/518) ENTERED: Scinu by GIARC & parter

Atty. for: 1 Escalar

Address: 3157 N. GILLINIA

City/State/Zip: Clicy, 1606/8

Telephone: (7.73) 539-8700

Dated:

Judge

SEP 2.2 2000

CLERKONOTHY BROWN

Judge's No.

DOROTHY BROWN, CLERKOF THE CIRCLE

WIY HE INGIS

Order 1801200 mg De 1500 4100 Uset 1935 12 ne February 1945 123 1250 9	(2/24/05) CCG N002
IN THE CIRCUIT COURT OF COOK COUNTY, ILLINOIS	30 6 6
GMAC Mortgage LLC	et erek Erek Segender
	CH 7418
Escobar, et al.	
DY FMAC to Universal Restoration Services shall by FMAC to Universal Restoration Services, only.  It is further ordered that Jorge Escobat to ENDORSE HIS WIFE'S NAME ON ANY SETTLEMENT DOCUMENT AND limited to check from AMA Insurance for \$39,272.01.	R IS ANTHORIZED
41250	NTERED Franklin Ulysea Valdenrama-1968
Name: Katz (aw Office, Ha (5t3) ENTERED: DEPUTY CLERK OF CO.	P 22 2009 THY BROWN K COUNTY GOURT
Atty. for: Description Dated:  Address: 3157 N California	Y, ñ <sup>OURT</sup>
City/State/Zip: Unap 160618 F Also  Felenhane: (773) 539-8700  Telenhane: (773) 539-8700	Judge's No.
Telephone: (773) 539-8700	

DOROTHY BROWN, CLERK OF THE CRCUIT COURT OF COOK COUNTY, HANOIS

## **EXHIBIT D**



## AGREEMENT BETWEEN OWNER AND CONTRACTOR

This Agreement made on: 10-	22-09		Job# 46288	
Between the Owner:			and work one are the same after only the rate one are and advantage	
Name: JORGE ESCOL Address: 9640 LARAM SKUKIE IL	HE ST	Project Address: (if different)	9640 LARAIN	11E ST
,	storation Services, Inc. CDrive 60090 ne following work, repair o th in the Estimate and Sci	ope or work or as inc	above mentioned project addicated below.	ddress
Scope of Work				
THE CONTRACT PRICE The cost for the project as specified in \$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	the Estimate documents act to additions and deduce Contractor pursuant the plan not received by the Contractor by Contractor to Contractor for that part operagraph shall not relieve such termination.	ayment schedule bei ntractor, Contractor s nder the provisions of the work performed the Owner of the ob	ove shall be set at the sum of horized change orders and low as work required by the shall have the right to stop wor this paragraph shalf not red prior to such termination.	allowances.  Contractor  ork_or  elieve the  Termination  otractor for
Down Payment	\$	1 PHYTEMES	Melajso po	THE HARMEN
Progress Payment at%	\$	. B. bandide	1 6 0 W 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Will Com
Final Balance Due Upon Completion	\$	1.11年15年 主要	1.11221 12	Jana Sant
WARRANTY At the completion of this project, and pa warranting the project for one year again  (	yment of the contract in function for the contract in function for the contract in workmanship.	II, Contractor shall e	xecute an instrument to Own	
- Congression of	Un /	iversal Restoration S		^
(Printed name)	<i>P</i>	AINIA. ILO	SPO AUUTS	KEW.